



report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER S ALL4
Colour	Grey
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 2

Date	2021-07-16
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-07
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-08-30
<b>MOT pass rate</b>	79 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	23
<b>Total items failed</b>	3

**MOT #14** 2023-08-16 06:27**MOT test number** 129941462440**Result** Passed**Next expiry date** 2024-08-30

- Advice** Suspension components corroded
- Advice** Engine covers and undertrays fitted
- Advice** Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.12 (f) (i))

**MOT #13** 2022-08-31 07:17**MOT test number** 811540689954**Result** Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))
- Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))
- Advice** Rear Brake hose has slight corrosion to ferrule nearside and offside (1.1.12 (f) (i))
- Advice** Engine covers and undertrays fitted

**MOT #12** 2021-08-31 11:52**MOT test number** 364538473412**Result** Passed

**MOT #11**

2020-11-23 13:41

**MOT test number**

585692155145

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2020-11-18 11:02

**MOT test number**

147389104665

**Result**

✗ Failed

**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Underside covered in mud unable to inspect**MOT #9**

2019-12-05 11:19

**MOT test number**

427134457490

**Result**

✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8**

2019-12-05 11:18

**MOT test number**

343333006494

**Result**

✗ Failed

**Pass with rectification** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7** 2018-12-05 13:11**MOT test number** 782912232387**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2017-11-16 11:54**MOT test number** 591244120291**Result** ✓ Passed**Advice** Front brake disc modified but not seriously weakened (3.5.1n)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-11-28 14:46**MOT test number** 256201773845**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake discs worn**MOT #4** 2015-11-16 15:07**MOT test number** 345761098225**Result** ✓ Passed**Advice** Centre Front Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Lower oil leak from oil pump solenoid valve wiring loom**MOT #3** 2014-12-08 14:10**MOT test number** 225542344315**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #2	2013-11-28 11:10
MOT test number	545862733384
Result	✓ Passed

MOT #1	2013-11-13 12:05
MOT test number	569087413311
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
30 August 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	30 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-12-09
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	2010-12-09	17 mi
Registration #2	2013-11-13	28.132 mi
Registration #3	2013-11-28	28.137 mi
Registration #4	2014-12-08	36.501 mi
Registration #5	2015-11-16	39.930 mi
Registration #6	2016-11-28	44.839 mi
Registration #7	2017-11-16	47.890 mi
Registration #8	2018-12-05	50.435 mi
Registration #9	2019-12-05	52.905 mi
Registration #10	2020-05-20	55.377 mi
Registration #11	2020-05-20	55.377 mi
Registration #12	2020-05-20	55.377 mi
Registration #13	2020-05-20	55.377 mi
Registration #14	2020-05-20	55.377 mi
Registration #15	2020-05-20	55.377 mi
Registration #16	2020-05-20	55.377 mi
Registration #17	2020-05-20	55.377 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1380 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2

**Engine number**

B0881800