



KU60HSZ


report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Blue
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-01-15
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #12	2024-01-24 11:23
MOT test number	121439904409
Result	✓ Passed
Next expiry date	2025-02-01

MOT #11	2023-02-02 15:41
MOT test number	566507624816
Result	✓ Passed

MOT #10	2021-12-21 13:00
MOT test number	621683714286
Result	✓ Passed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Boot split leaking grease (6.1.7 (g) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Bald outer edge (5.2.3 (e))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Bald outer edge (5.2.3 (e))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #9** 2021-12-17 16:58**MOT test number** 346493313888**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Bald outer edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Boot split leaking grease (6.1.7 (g) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect kick up on wrong side (4.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Bald outer edge (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2020-11-26 13:37**MOT test number** 137403585507**Result** ✓ Passed**MOT #7** 2020-11-19 11:51**MOT test number** 546229563112**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #6** 2019-06-11 11:08**MOT test number** 502340327231**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #5** 2018-05-29 15:57**MOT test number** 355099639263**Result** ✓ Passed**Advice** Offside Front Inner drive shaft boot slightly deteriorated**MOT #4** 2017-06-06 10:35**MOT test number** 694444192175**Result** ✓ Passed**Advice** Offside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2016-06-23 10:48**MOT test number** 912535062247**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-11-03 15:54**MOT test number** 298307404397**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Outer Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-11-06 15:45**MOT test number** 349450013373**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
1 February 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-11-19
Last registration	2024-01-24
Complete history	See info



Registration #1	2010-11-19	18 mi
Registration #2	2013-11-06	46.349 mi
Registration #3	2014-11-03	65.143 mi
Registration #4	2016-06-23	89.183 mi
Registration #5	2017-06-06	102.315 mi
Registration #6	2018-05-29	113.523 mi
Registration #7	2019-06-11	126.609 mi
Registration #8	2020-05-29	131.277 mi
Registration #9	2021-05-29	131.277 mi
Registration #10	2022-05-29	131.277 mi
Registration #11	2023-05-29	131.277 mi
Registration #12	2024-01-24	131.277 mi
Registration #13	2024-01-24	131.277 mi
Registration #14	2024-01-24	131.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2286 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWT4004886