



CITROËN




report date: 2024-03-29

## General information

Make	CITROEN
Model	C2 AIRPLAY PLUS
Colour	Red
Year of manufacture	2007
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.300 rpm
Engine capacity	1.124 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-26
Pictures	7
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-02-20
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	1

MOT #17	2023-02-21 14:10
MOT test number	806972218984
Result	✓ Passed
Next expiry date	2024-02-20
Advice	Nearside Front tyre slightly wearing on outer edge

MOT #16	2022-02-15 10:52
MOT test number	278444582918
Result	✓ Passed

**MOT #15** 2022-01-12 11:54**MOT test number** 711199065511**Result** ✗ Failed**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**MAJOR** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Coolant leak**Advice** Items removed from driver's view prior to test**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill panel (5.3.6 (a) (i))**Advice** Spare tyre defective flat**MOT #14** 2021-01-12 12:05**MOT test number** 597569327148**Result** ✓ Passed**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #13** 2019-07-19 13:09**MOT test number** 383217341770**Result** ✓ Passed**MOT #12** 2019-07-17 11:57**MOT test number** 207013008193**Result** ✗ Failed**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #11** 2018-09-17 12:24**MOT test number** 847836983026**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Service brake binding but not excessively both rear (1.2.1 (f))**MOT #10** 2017-08-01 11:13**MOT test number** 331633748781**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #9** 2016-08-04 12:02**MOT test number** 463711744344**Result** ✓ Passed**MOT #8** 2015-08-25 12:19**MOT test number** 249113552253**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened rusty and pitted (3.5.1i)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened rusty and pitted (3.5.1i)**MOT #7** 2015-02-23 16:05**MOT test number** 285324855055**Result** ✓ Passed**Notice** Offside rear wheel bearing slightly noisy

**MOT #6** 2014-02-14 13:53**MOT test number** 829825344021**Result** ✓ Passed**MOT #5** 2013-02-18 16:50**MOT test number** 817409043066**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2013-02-13 11:49**MOT test number** 959304943000**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #3** 2012-02-13 09:17**MOT test number** 708094842079**Result** ✓ Passed**MOT #2** 2011-02-02 10:40**MOT test number** 939423831075**Result** ✓ Passed



MOT #1	2010-02-13 13:50
MOT test number	394754840011
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc slightly scored (3.5.1h)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-06
Last registration	2023-02-21
Complete history	<a href="#">See info</a>



Registration #1	2007-01-06	14 mi
Registration #2	2010-02-13	31.377 mi
Registration #3	2011-02-02	37.807 mi
Registration #4	2012-02-13	42.409 mi
Registration #5	2013-02-13	47.125 mi
Registration #6	2013-02-18	47.125 mi
Registration #7	2014-02-14	56.815 mi
Registration #8	2015-02-23	67.117 mi
Registration #9	2015-08-25	68.971 mi
Registration #10	2016-08-04	70.578 mi
Registration #11	2016-08-04	70.578 mi
Registration #12	2016-08-04	70.578 mi
Registration #13	2016-08-04	70.578 mi
Registration #14	2016-08-04	70.578 mi
Registration #15	2016-08-04	70.578 mi
Registration #16	2016-08-04	70.578 mi
Registration #17	2016-08-04	70.578 mi
Registration #18	2016-08-04	70.578 mi
Registration #19	2016-08-04	70.578 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1659 mm
Height	1477 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7W4926126