





report date: 2024-03-28

## General information

Make	AUDI
Model	A5 TDI QUATTRO S LINE
Colour	White
Year of manufacture	2016
Top speed	146 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	187 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



# Internet history

Er	١tr	v	2

Entry 2	
Date	2021-10-23
Pictures	0
Listing price	<u>View report</u>

#### source: autotrader.co.uk

#### Entry 1

Lifting 1	
Date	2021-08-30
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-11-15
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #10	2023-11-16 10:53
MOT test number	255412806087
Result	✓ Passed
Next expiry date	2024-11-15
Advice Rear Sub-frame is corroded but structural rigidity is not significantly reduce	ced (6.1.1 (c) (i))
Advice Front Upper Suspension arm pin or bush worn but not resulting in excessi (5.3.4 (a) (i))	ve movement both sides
Advice Front Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (	(e))

MOT #9	2022-11-16 15:18
MOT test number	247267526278
Result	✓ Passed
MOT #8	2022-11-11 15:32
MOT test number	516571767481
Result	<b>×</b> Failed
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #7	2021-11-10 14:40
MOT test number	513318352665
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MOT #6** 2021-03-12 10:48

**MOT test number** 737775005261

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

Advice Rear Inner Tyre worn close to legal limit/worn on edge worn inner edges both side (5.2.3 (e))

MOT #5 2021-03-12 10:48

MOT test number 823888394821

Result X Failed

**Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))

Advice Rear Inner Tyre worn close to legal limit/worn on edge worn inner edges both side (5.2.3 (e))

**Pass with rectification** Front Headlamp cleaning device for LED or HID headlamp inoperative both side (4.1.6 (a) (ii))

MOT #4 2020-02-27 11:22

MOT test number 689492272744

Result \( \sqrt{Passed} \)

MOT #3 2020-02-26 12:15

MOT test number 115640213171

**Result** ★ Failed

Fail Offside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Fail Nearside Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

**MOT #2** 2019-02-27 10:01

MOT test number 833359099977

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/12



MOT #1 2019-02-20 14:28

**MOT test number** 237642748779

Result

**x** Failed

Fail

Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



$\sim$			1- 3		L .	
U	wr	ıer	n	IS	το	ır٧

C Miles Miscory	
For how long did the current and previous owner(s) have this AUDI? How many owners defect it in the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-03-22
Last registration	2023-11-16
Complete history	See info



Registration #1	2016-03-22	10 mi
Registration #2	2019-02-20	56.316 mi
Registration #3	2019-02-27	56.736 mi
Registration #4	2020-02-26	81.606 mi
Registration #5	2020-02-27	81.611 mi
Registration #6	2021-03-12	89.632 mi
Registration #7	2021-03-12	89.632 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		D.277 es

More info >

CarCheck.co.uk page 11/12



# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	87%
Pedestrian	74%
Safety systems	86%
Overall rating	88%
Video	see crash video



# Dimensions & weight

Width	1854 mm
Height	1372 mm
Length	4626 mm
Wheel base	2751 mm
Kerb weight	1590 kg
Max. allowed weight	2090 kg

# Additional information

Fuel tank capacity	63 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page 12	2/12

Number of axles 2

Engine number CNHA199087