



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Red
Year of manufacture	-
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg







LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-03
Pictures	11
Listing price	View report



source: cargurus.co.uk

**MOT history****MOT #19**

2023-03-23 10:37

MOT test number

722449990000

Result

✗ Failed

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Power steering malfunctioning (2.1.5 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18

2021-07-06 11:01

MOT test number

338306854486

Result

✓ Passed

MOT #17

2020-08-26 11:07

MOT test number

797302461078

Result

✓ Passed

- Advice** Three wheel trim covers fitted n/s front missing.
- Advice** Items removed from driver's view prior to test
- Advice** Under trays fitted.
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #16**

2020-08-25 09:34

MOT test number

943671688547

Result**✗ Failed**

- Advice** Three wheel trim covers fitted n/s front missing.
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Under trays fitted.
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Items removed from driver's view prior to test
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #15**

2019-08-20 08:55

MOT test number

118944124163

Result

✓ Passed

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Items removed from driver's view prior to test**Advice** Four wheel trim covers fitted.**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Under trays fitted.**MOT #14**

2018-09-01 09:09

MOT test number

869610457374

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Under trays fitted.**Advice** Four wheel trim covers fitted.**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #13**

2018-09-01 09:09

MOT test number

241701036381

Result**✗ Failed****Pass with rectification**

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Four wheel trim covers fitted.

Advice

Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Under trays fitted.

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12

2017-08-31 15:33

MOT test number

758987034896

Result**✓ Passed****Advice**

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Vehicle under trays fitted

Advice

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner rear bush (2.4.G.2)

Advice

Rear exhaust slightly deteriorated

**MOT #11**

2017-08-31 10:56

MOT test number

107891051192

Result**✗ Failed****Advice**

Central Exhaust has a minor leak of exhaust gases (7.1.2)

Advice

Nearside Rear Nail in tyre

Fail

Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice

Rear exhaust slightly deteriorated

Advice

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner rear bush (2.4.G.2)

Advice

Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

Fail

Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice

Vehicle under trays fitted

MOT #10

2016-08-31 13:05

MOT test number

499511329993

Result**✓ Passed****Advice**

Under trays fitted

Advice

Offside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice

Offside Rear tyre worn slightly on inner tread

**MOT #9** 2016-08-31 10:23**MOT test number** 769116411419**Result** ✗ Failed

- Advice** Under trays fitted
- Advice** Offside Front Tyre worn close to the legal limit worn bald on inner tread (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Spare tyre under-inflated
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Parking brake lever has long travel
- Advice** Offside Rear tyre worn slightly on inner tread
- Advice** Nearside Front Tyre worn close to the legal limit worn bald on inner tread (4.1.E.1)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Coolant level below min mark
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #8 2015-08-25 15:17**MOT test number** 537350258642**Result** ✓ Passed

- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Four wheel trim covers fitted. under trays fitted.
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #7** 2015-08-24 18:00**MOT test number** 528810539953**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Four wheel trim covers fitted. under trays fitted.**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**MOT #6** 2014-08-29 13:30**MOT test number** 378161144274**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Four wheel trim covers fitted.**Advice** Offside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components

**MOT #5**

2014-08-28 19:30

MOT test number

865740844248

Result**✗ Failed**

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Notice** Items removed from driver's view prior to test
- Advice** Offside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Four wheel trim covers fitted.
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4

2013-08-29 12:22

MOT test number

637051943277

Result**✓ Passed**

- Notice** Four wheel trims fitted.
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2012-08-30 14:50**MOT test number** 386833542215**Result** ✓ Passed**Notice** Cuts in o/s rear tyre but not reaching the cords.**MOT #2** 2012-08-30 11:18**MOT test number** 136053142221**Result** ✗ Failed**Notice** Cuts in o/s rear tyre but not reaching the cords.**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2011-08-23 14:48**MOT test number** 869355531274**Result** ✓ Passed**Notice** Front tyres wearing low on edges



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-01
Last registration	2023-03-23
Complete history	See info



Registration #1	2008-09-01	22 mi
Registration #2	2011-08-23	16.779 mi
Registration #3	2012-08-30	24.690 mi
Registration #4	2012-08-30	24.690 mi
Registration #5	2013-08-29	34.688 mi
Registration #6	2014-08-28	42.405 mi
Registration #7	2014-08-29	42.405 mi
Registration #8	2015-08-24	52.090 mi
Registration #9	2015-08-25	52.090 mi
Registration #10	2016-08-31	67.233 mi
Registration #11	2016-08-31	67.233 mi
Registration #12	2016-08-31	67.233 mi
Registration #13	2016-08-31	67.233 mi
Registration #14	2016-08-31	67.233 mi
Registration #15	2016-08-31	67.233 mi
Registration #16	2016-08-31	67.233 mi
Registration #17	2016-08-31	67.233 mi
Registration #18	2016-08-31	67.233 mi
Registration #19	2016-08-31	67.233 mi
Registration #20	2016-08-31	67.233 mi
Registration #21	2016-08-31	67.233 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141