



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L2H1 CDTi S/S
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-01
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-17
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	22
Total items failed	11

MOT #12	2023-07-18 16:39
MOT test number	371037599224
Result	✓ Passed
Next expiry date	2024-07-17

MOT #11	2023-07-15 13:35
MOT test number	215940535398
Result	✗ Failed

- Fail

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail

Central Rear Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice

Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail

Central Rear Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail

Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10** 2022-06-27 08:50**MOT test number** 241986969813**Result** ✓ Passed**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2022-06-27 08:50**MOT test number** 816414186470**Result** ✗ Failed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2021-07-14 14:50**MOT test number** 143317454664**Result** ✓ Passed**MOT #7** 2021-07-06 12:01**MOT test number** 595736493045**Result** ✗ Failed**Fail** Offside Front Suspension rod ball joint excessively worn Link rod (5.3.4 (a) (i))**Fail** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn Axle front bush as marked (5.1.2 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension rod ball joint excessively worn Link rod (5.3.4 (a) (i))**Fail** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn Front bush as marked (5.1.2 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2021-03-02 09:14

MOT test number

421677188118

Result

✓ Passed

Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view cracked n/s/f (3.2 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

2021-03-01 10:14

MOT test number

640740087026

Result

✗ Failed

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view cracked n/s/f (3.2 (a) (i))

MOT #4

2020-03-04 09:00

MOT test number

324766768511

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #3** 2019-03-07 10:42**MOT test number** 307250456725**Result** ✓ Passed

- Advice** Application of front brakes uneven but less than 30%
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2018-03-19 08:03**MOT test number** 587455962823**Result** ✓ Passed**MOT #1** 2018-03-13 11:03**MOT test number** 587005319891**Result** ✗ Failed

- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
17 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2015-01-01
Current registration	 XXXXXX
Plate since	2015-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-03-31
Last registration	2023-07-18
Complete history	See info



Registration #1	2015-03-31	27 mi
Registration #2	2018-03-13	57.032 mi
Registration #3	2018-03-19	57.343 mi
Registration #4	2019-03-07	77.696 mi
Registration #5	2020-03-04	90.980 mi
Registration #6	2021-03-01	103.065 mi
Registration #7	2021-03-02	103.066 mi
Registration #8	2023-07-18	103.066 mi
Registration #9	2023-07-18	103.066 mi
Registration #10	2023-07-18	103.066 mi
Registration #11	2023-07-18	103.066 mi
Registration #12	2023-07-18	103.066 mi
Registration #13	2023-07-18	103.066 mi
Registration #14	2023-07-18	103.066 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1880 mm
Length	4740 mm
Kerb weight	1370 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	198A30007269688 LJ5