



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-07-10
Pictures	1
Listing price	<a href="#">View report</a>

**AA**

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-16
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	12
Total items failed	2

## MOT #14 2023-07-17 09:04

MOT test number 147162062418

Result ✓ Passed

Next expiry date 2024-07-16

**Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Nail in tyre ## ATTENTION REQUIRED ##**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

## MOT #13 2022-07-07 10:40

MOT test number 194156728388

Result ✓ Passed

## MOT #12 2021-08-17 15:01

MOT test number 755149470806

Result ✓ Passed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Both Rear Inner Sills Corroded**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11** 2020-07-29 10:37**MOT test number** 963458450950**Result** ✓ Passed**MOT #10** 2020-07-29 10:37**MOT test number** 726193011035**Result** ✗ Failed**Pass with rectification** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #9** 2019-08-21 10:09**MOT test number** 963171896103**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #8** 2018-08-21 13:11**MOT test number** 885730767894**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2017-08-08 09:46**MOT test number** 537496713030**Result** ✓ Passed**Advice** Nearside Front wiper blade slightly torn but cleans windscreen effectively**Advice** Oil leak gearbox**Advice** Nearside Rear Nail in tyre

**MOT #6** 2016-08-22 08:41**MOT test number** 499385781617**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-08-21 08:39**MOT test number** 822932330374**Result** ✓ Passed**MOT #4** 2014-08-12 10:45**MOT test number** 868094024294**Result** ✓ Passed**MOT #3** 2013-08-05 14:40**MOT test number** 886887613250**Result** ✓ Passed**MOT #2** 2013-08-05 14:40**MOT test number** 389007713284**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #1** 2011-11-29 12:47**MOT test number** 496843631363**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
16 July 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	16 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>CK58WAU</b>
Plate since	2019-06-29
Current registration	<b>CK58WAU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-01-30
Last registration	2023-07-17
Complete history	<a href="#">See info</a>



Registration #1	2009-01-30	21 mi
Registration #2	2011-11-29	5.471 mi
Registration #3	2013-08-05	6.101 mi
Registration #4	2014-08-12	8.112 mi
Registration #5	2015-08-21	10.239 mi
Registration #6	2016-08-22	12.603 mi
Registration #7	2017-08-08	14.851 mi
Registration #8	2018-08-21	17.004 mi
Registration #9	2019-08-21	19.157 mi
Registration #10	2020-08-21	21.310 mi
Registration #11	2021-08-21	23.463 mi
Registration #12	2022-08-21	25.616 mi
Registration #13	2023-08-21	27.769 mi
Registration #14	2024-08-21	29.922 mi
Registration #15	2025-08-21	32.075 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1096095