





General information

Make	VAUXHALL
Model	MOKKA DESIGN NAV ECOTEC S/S
Colour	Black
Year of manufacture	2018
Top speed	122 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	138 BHP
Max. torque	200 Nm at 4.900 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 11	
Date	2021-11-25
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 10	
Date	2021-11-19
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 9	
Date	2021-10-29
Pictures	26
Listing price	View report



source: autotrader.co.uk

Entry 8	
Date	2021-10-28
Pictures	26
Listing price	View report









source: autotrader.co.uk

Entry 7	
Date	2021-10-24
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 6	
Date	2021-10-14
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 5	
Date	2021-10-03
Pictures	0
Listing price	View report

source: heycar.co.uk

Entry 4	
Date	2021-09-30
Pictures	26
Listing price	View report



source: autotrader.co.uk







Date	2021-09-18
Pictures	10
Listing price	View report



source: autoonline.co.uk

Entry 2	
Date	2021-09-09
Pictures	26
Listing price	View report



source: heycar.co.uk


Entry	1
-------	---

Date Pictures 2021-09-06

26

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	3
Total items failed	3

MOT #5 2	023-08-19 09:00
MOT test number	907819225780
Result	🗸 Passed
Next expiry date	2024-09-01
Advice Front Exhaust has a minor leak of exhaust gases flexi pipe deteriorated (6.1.2 (a))	

МОТ #4	2023-08-18 11:47
MOT test number	381703129790
Result	× Failed
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Offside Windscreen wiper blade defective (3.4 (b) (i))	
Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Front Exhaust has a minor leak of exhaust gases flexi pipe deteriorated (6.1.2 (a	a))

MOT #3	2022-08-24 08:36
MOT test number	784328399401
Result	✓ Passed





MOT #2	2021-09-02 08:40
MOT test number	524542847663
Result	✓ Passed
MOT #1	2021-08-25 10:49
MOT test number	242850745672
Result	✓ Passed



Tax & MOT check

✓ Taxed	мот
Tax due: 1 August 2024	Expires: 1 September 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	A AMPLE
Date	× · · · · · · · · · · · · · · · · · · ·
Category	AMP
Туре	

Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
And and a second s	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



SG68RDX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2018-09-03
Last registration	2023-08-19
Complete history	<u>See info</u>



Registration #1	2018-09-03	22 mi
Registration #2	2021-08-25	19.974 mi
Registration #3	2021-09-02	20.121 mi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi

More info \rightarrow





Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	2038 mm
Height	1658 mm
Length	4275 mm
Wheel base	2555 mm
Kerb weight	1319 kg
Max. allowed weight	1828 kg
Additional information	
Additional information Fuel tank capacity	53 l
	53 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5