





report date: 2024-03-29

General information

Make	AUDI
Model	TT TFSI
Colour	Black
Year of manufacture	2007
Top speed	149 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	200 BHP	
Max. torque	280 Nm at 1.800 rpm	
Engine capacity	1.984 сс	
Cylinders	4	
Fuel type	Petrol	
Consumption city	26.4 mpg	
Consumption extra urban	47.1 mpg	
Consumption combined	36.7 mpg	
CO2 emission	183 g/km	
CO2 label	I	



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history

Entry 1

Date 2021-01-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-04-11
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	22
Total items failed	8

MOT #21	2024-04-08 14:08
MOT test number	306393962429
Result	✓ Passed
Next expiry date	2025-04-11

MOT #20	2023-04-06 10:24	
MOT test	number 807307780299	
Result	✓ Passed	
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #19		2023-04-06 08:48
MOT test	number	964579955780
Result		X Failed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		akened (1.1.14 (a) (ii))
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		eakened (1.1.14 (a) (ii))
	earside Front Drive shaft joint constant velocity boot split or insecure, dirt (6.1.7 (g) (ii))	no longer prevents the

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #18 2022-04-04 13:25

MOT test number 417527379386

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs pitted, scored and lipped (1.1.14 (a) (ii))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs lipped, scored (1.1.14 (a) (ii))

MOT #17 2022-04-04 09:58

MOT test number 850236032283

Result X Failed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear discs lipped, scored (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both front discs pitted, scored and lipped (1.1.14 (a) (ii))

MOT #16 2021-04-12 09:15

MOT test number 390361289627

Result

Passed

Advice Under body covers fitted

MOT #15 2020-05-01 10:47

MOT test number 603231327735

Result \(\sqrt{Passed} \)

Advice Offside Rear Nail in tyre

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #14 2020-05-01 10:47

MOT test number 309766326660

Result X Failed

Advice Offside Rear Nail in tyre

Pass with rectification Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #13 2019-05-16 09:07

MOT test number 117345061079

Result
✓ Passed

MOT #12 2018-06-25 17:31

MOT test number 242535988459

Result ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11 2018-06-25 13:59

MOT test number 884986013120

Result X Failed

Fail Nearside Rear Position lamp not working (4.2.1 (a))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2017-06-26 14:08

MOT test number 884126663783

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #9 2017-06-23 08:52

MOT test number 720655179545

Result × Failed

Fail Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #8 2016-04-16 08:18

MOT test number 636014699543

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-04-16 13:52

MOT test number 638036605137

Result \sqrt{Passed}

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2015-04-16 09:47

MOT test number 265346905444

Result X Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5 2014-02-03 10:10

MOT test number 866904034068

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #4 2013-02-08 09:24

MOT test number 829319433004

Result ✓ Passed

MOT #3 2012-02-06 15:08

MOT test number 415757232044

Result ✓ Passed

MOT #2 2011-02-10 15:12

MOT test number 487901541043

Result ✓ Passed

MOT #1 2011-02-10 13:10

MOT test number 727921241070

Result X Failed

Fail Nearside Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this AUDI? How many owners di Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	NK SILVE
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-09-01
Last registration	2024-04-08
Complete history	See info



Registration #1	2007-09-01	22 mi
Registration #2	2011-02-10	38.805 mi
Registration #3	2011-02-10	38.805 mi
Registration #4	2012-02-06	45.379 mi
Registration #5	2013-02-08	50.024 mi
Registration #6	2014-02-03	52.051 mi
Registration #7	2015-04-16	62.357 mi
Registration #8	2015-04-16	62.357 mi
Registration #9	2016-04-16	69.577 mi
Registration #10	2017-06-23	75.202 mi
Registration #11	2017-06-26	75.203 mi
Registration #12	2018-06-25	78.745 mi
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.77 es
Registration #18		11.777 es
Registration #19		9.77 es
Registration #20		11.777 es
Registration #21		D.777 es
Registration #22		71.777 es
Registration #23		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1260 kg
Max. allowed weight	1660 kg

Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page	14/14

Number of axles 2

Engine number BWA 113801