





report date: 2024-03-29

General information

Make	VAUXHALL
Model	ASTRA TECH LINE NAV ECOTEC S/S
Colour	Grey
Year of manufacture	2019
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	170 Nm at 1.800 rpm
Engine capacity	999 сс
Cylinders	3
Fuel type	Petrol
Consumption combined	48.7 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-30

Pictures 40

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-10
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #5		2024-03-06 17:38
MOT test	number	302695014422
Result		✓ Passed
Next expiry date 2025-03-10		
Advice Offside Rear Tyre slightly damaged/cracking or perishing and getting close to wear markers (5.2.3 (d) (ii))		ose to wear markers (5.2.3
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #4		2024-03-06 08:33
MOT test num	ıber	706160166283
Result		X Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm 225/45/17 (5.2.3 (e)) Advice Offside Rear Tyre slightly damaged/cracking or perishing and getting close to wear markers (5.2.3 (d) (ii))		
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge advise to replace asap (5.2.3 (e))		

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2023-03-10 13:44 **MOT** test number 601478212579 Result ✓ Passed **Advice** Front and rear brake pads over half worn **Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing 225/45/17 (5.2.3 (d) (ii)) Front wiper blades deteriorating Advice Advice Offside Front Service brake binding but not excessively (1.2.1 (f)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened and rear offside and nearside (1.1.14 (a) (ii)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner wall very slight crack (5.2.3 (d) (ii))

MOT #2

MOT test number

400299988719

Result

Advice

Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1	2021-06-15 16:58
MOT test number	102151840279
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

<u> </u>	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NIE. ALE
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-06-17
Last registration	2024-03-06
Complete history	See info



Registration #1	2019-06-17	27 mi
Registration #2	2021-06-15	12.144 mi
Registration #3		11.777 es
Registration #4	2022-03-11	17.771 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 mi

More info >

CarCheck.co.uk page 10/11



DF19DGZ report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	86%
Children	84%
Pedestrian	83%
Safety systems	75%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1485 mm
Length	4370 mm
Max. allowed weight	1780 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	B1191209JGDX0235LE1

CarCheck.co.uk page 11/11