





General information

Make	ΤΟΥΟΤΑ
Model	PROACE L2H1 HDI 1200 P/V
Colour	White
Year of manufacture	2013
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP	0 < 101 A
Max. torque	320 Nm at 2.000 rpm	101 - 120 ^B _C
Engine capacity	1.997 cc	121 - 140 P
Cylinders	4	141 - 165 F
Fuel type	Diesel	
Consumption city	37.2 mpg	186 - 225 J
Consumption extra urban	48.7 mpg	225+ L
Consumption combined	44.1 mpg	
CO2 emission	168 g/km	
CO2 label	Н	





Internet history Entry 3 Date 2022-06-18 Pictures 0 Listing price View report

source: cargurus.co.uk

Entry 2

Date	2021-11-18	
Pictures	19	
Listing price	View report	



source: yesauto.com

Entry 1	
Date	2021-06-30
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-13
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	17
Total items failed	11

MOT #12	2024-01-29 14:18
MOT test number	869776270875
Result	✓ Passed
Next expiry date	2025-02-13
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))
Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11	2023-02-14 11:21
MOT test number	983204483670
Result	✓ Passed

MOT #10	2023-02-14 11:21
MOT test number	237908076604
Result	× Failed
Pass with rectification	Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1
(b) (ii))	

MOT #9	2022-01-08 12:08
MOT test number	314228689733
Result	✓ Passed



MOT #8	2020-11-17 14:37
MOT test number	633054127793
Result	✓ Passed
AdviceWear outer edge o/s rear tyreAdviceEngine mounting damaged but not to excess (6.1.8 (a) (i))AdviceOffside wiper split	
MOT #7	2020-11-17 14:37
MOT test number	387691942443
Result	🗙 Failed
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	

1 435 WIL	Activitie Activitie Activities and the analysis (4.1.2 (4))
Advice	Offside wiper split
Advice	Engine mounting damaged but not to excess (6.1.8 (a) (i))
Advice	Wear outer edge o/s rear tyre
	Advice Advice

MOT #6		2019-11-12 16:36
MOT test	number	168959928250
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #5	2019-11-12 13:29
MOT test number	850318771859
Result	🗙 Failed
Fail Nearside Front Outer Prop shaft joint constant velocity boot no longer prevents the (6.1.7 (g) (ii))	ingress of dirt
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Registration plate lamp inoperative in the case of a single lamp or all lamps	s (4.7.1 (b) (ii))
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamp	ps (4.7.1 (b) (ii))

МОТ #4	2018-11-22 16:13
MOT test number	705789173823
Result	✓ Passed

MOT #3	2017-11-03 16:31
MOT test number	185182230776
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2017-11-03 13:22
MOT test number	638502019031
Result	🗙 Failed
Fail Offside Front constant velocity joint gaiter damaged to the extent that it no long ingress of dirt etc (2.5.C.1a)	ger prevents the
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Front Suspension arm ball joint dust cover excessively deteriorated so t prevents the ingress of dirt (2.4.G.2)	hat it no longer
Fail Offside Headlamp aim too high (1.8)	
Fail Nearside Front Suspension arm ball joint dust cover excessively deteriorated so prevents the ingress of dirt (2.4.G.2)	that it no longer
MOT #1	2016-11-05 11:27
MOT test number	994475027636

Result Passed Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 13 February 2025
Tax status	Valid until 1 October
Days left	154
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 11.111
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-11-01
Last registration	2024-01-29
Complete history	See info



Registration #1	2013-11-01	11 mi
Registration #2	2016-11-05	48.062 mi
Registration #3	2017-11-03	58.566 mi
Registration #4	2017-11-03	58.566 mi
Registration #5	2018-11-22	74.883 mi
Registration #6	2019-11-12	89.719 mi
Registration #7	2019-11-12	89.719 mi
Registration #8	2020-11-17	107.255 mi
-		
Registration #9		11.117 mi
-		11.227 est
Registration #9		01.000 esi 01.000 esi 01.000 esi
Registration #9 Registration #10		01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9Registration #10Registration #11Registration #12Registration #13		01,000 460 01,000 460 01,000 460 01,000 460 01,000 460 01,000 460 01,000 460

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1986 mm
Height	1942 mm
Length	5135 mm
Wheel base	3120 mm
Kerb weight	1829 kg
Max. allowed weight	2932 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	RH04063847