





report date: 2024-03-28

## General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Silver
Year of manufacture	2004
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/15



report date: 2024-03-28

## Internet history

## Entry 2

Date 2021-06-29

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-25	
------	------------	--

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2021-09-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	41
Total items failed	11

MOT #19	2020-09-08 14:33
MOT test number	652762745817
Result	✓ Passed
Next expiry date	2021-09-07
Advice Nearside Front Tyre worn clo	ose to legal limit/worn on edge (5.2.3 (e))
Minor Offside Windscreen wiper bla	de defective (3.4 (b) (i))
Advice Offside Headlamp has a prod (b))	duct on the light source but not seriously reducing light output (4.1.4
Advice Rear Tyre worn close to lega	al limit/worn on edge Both (5.2.3 (e))
Minor Offside Front Obligatory mirro	or slightly damaged (3.3 (b) (i))
<b>Advice</b> Brake disc worn, pitted or so	cored, but not seriously weakened (1.1.14 (a) (ii))
Advice Coil spring corroded (5.3.1 (	b) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #18** 2020-09-08 14:33 **MOT** test number 943065736452 Result × Failed Minor Offside Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Coil spring corroded (5.3.1 (b) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i)) Offside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 **Advice** (b)) Advice Rear Tyre worn close to legal limit/worn on edge Both (5.2.3 (e)) **Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #17

MOT test number

769882603874

Result

Advice Slight Accident Damage to Near Side of Front Bumper

MOT test number

Result

Fail Exhaust has a major leak of exhaust gases Rear Exhaust Pipe Broken and Insecure (6.1.2 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Slight Accident Damage to Near Side of Front Bumper

MOT #15	2018-03-16 16:34
MOT test number	927298640553
Result	✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-28

**MOT #14** 2018-03-14 15:26

**MOT test number** 672910111860

Result X Failed

**Fail** Offside front brake binding (3.7.B.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

**Fail** Offside Headlamp aim beam image obviously incorrect Dip Beam Bulb Fitted Wrongly ... Beam Image Incorrect (1.8.A.1b)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Headlamp aim beam image obviously incorrect Dip Beam Bulb Fitted Wrongly ... Beam Image Incorrect (1.8.A.1b)

**MOT #13** 2017-03-15 11:27

MOT test number 135197534541

**Result** 
✓ Passed

**Advice** Rear boot full

Advice Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)

**Advice** Eml illuminated

Advice Offside Front head lamp misted

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)

CarCheck.co.uk page 5/15



report date: 2024-03-28

**MOT #12** 2017-03-14 12:06 **MOT** test number 379720576235 Result **★** Failed Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3) Advice Rear registration plate delaminated but not likely to be misread (6.3.1d) **Advice** Rear boot full Fail Rear Brake pipe excessively corroded to flexi both nsr\osr (3.6.B.2c) Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f) Advice Child Seat fitted not allowing full inspection of adult belt Advice Eml illuminated Advice Offside Side repeater slightly discoloured (1.4.A.2f) Advice Offside Front head lamp misted

MOT #11	2016-03-04 15:46
MOT test number	108381457908
Result	✓ Passed
MOT #10	2016-03-02 15:27
MOT test number	286069105353
Result	<b>X</b> Failed
Fail Offside rear brake binding (3.7.B.1)	
Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)	

MOT #9	2015-03-03 12:59
MOT test number	938062465030
Result	<b>✓</b> Passed
Notice O/s rear brakes binding slightly	

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #8	2014-02-14 12:54
MOT test number	936535044003
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2013-03-01 09:31
MOT test number	385860663049
Result	✓ Passed
MOT #6	2012-02-28 15:05
MOT test number	426759552018
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice High level stop lamp not working	
Notice Engine mangment light on	
Advice Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #5	2011-02-22 11:08
MOT test number	615223751053
Result	✓ Passed
Notice Front offside/nearside brake disc slight corroded	

MOT #4	2010-02-23 12:07
MOT test number	170174150413
Result	✓ Passed
MOT #3	2009-02-18 10:43
MOT test number	900769149078
Result	✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #2

MOT test number

984139858089

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

MOT test number

423970557095

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Engine warning lamp on

CarCheck.co.uk page 8/15



report date: 2024-03-28

#### Tax & MOT check



X MOT

Tax expired: 6 July 2021

**Expired:** 7 September 2021

Tax status	Expired at 6 July 2021
Days left	1027 days too late
MOT expiry date	7 September 2021
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 9/15



report date: 2024-03-28

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



furthe scinors

**AK04AYG** 

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this TOYOTA had different number plates. ober of plates

CarCheck.co.uk page 12/15



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-03-01
Last registration	2020-09-08
Complete history	See info



Registration #1	2004-03-01	6 mi
Registration #2	2007-02-19	87.332 mi
Registration #3	2008-02-28	91.684 mi
Registration #4	2009-02-18	95.233 mi
Registration #5	2010-02-23	99.252 mi
Registration #6	2011-02-22	102.045 mi
Registration #7	2012-02-28	105.722 mi
Registration #8	2013-03-01	107.709 mi
Registration #9	2014-02-14	108.469 mi
Registration #10	2015-03-03	109.287 mi
Registration #11	2016-03-02	109.890 mi
Registration #12		11.777 ea
Registration #13		11.777 es
Registration #14		11.777 ea
Registration #15		11.177 mi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 ea
Registration #19		11.777 mi
Registration #20		11.777 es
Registration #21		11,777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 14/15



## Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

**Engine number** 3ZZU520898