



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA SE
Colour	Blue
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	14.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 2

Date	2023-10-13
Pictures	14
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-10-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	14
Total items failed	4

MOT #132023-09-28 15:40

MOT test number462072613757

Result✓ Passed

Next expiry date2024-10-05

- Advice** Rear Brake pipe corroded, covered in grease or other material nearside and offside corroded along rear axle to wheel cylinders (1.1.11 (c))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge no visible tread on inner edge and has nail in tyre (5.2.3 (e))
- Advice** Front Brake pipe corroded, covered in grease or other material nearside and offside corroded to flexi hoses (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm back bush worn and badly perished (5.3.4 (a) (i))

**MOT #12**

2023-09-25 16:36

MOT test number

298543751749

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge no visible tread on inner edge and has nail in tyre (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear Brake pipe corroded, covered in grease or other material nearside and offside corroded along rear axle to wheel cylinders (1.1.11 (c))

Fail Nearside Front Tyre has ply or cords exposed cord exposed on outer edge (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm back bush worn and badly perished (5.3.4 (a) (i))

Advice Front Brake pipe corroded, covered in grease or other material nearside and offside corroded to flexi hoses (1.1.11 (c))

Fail Offside Front Suspension arm pin or bush excessively worn lower arm back bush separated from arm (5.3.4 (a) (i))

MOT #11

2022-10-06 13:45

MOT test number

873636839908

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10

2022-10-04 11:21

MOT test number

215664305611

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #9

2021-09-14 10:15

MOT test number

103894096981

Result

✓ Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #8	2020-09-29 13:19
---------------	------------------

MOT test number	447190116580
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2020-07-16 13:15
---------------	------------------

MOT test number	949911433335
------------------------	--------------

Result	✓ Passed
---------------	----------

Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))
--------------	--

MOT #6	2019-08-02 09:21
---------------	------------------

MOT test number	197582604400
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2018-08-02 14:35
---------------	------------------

MOT test number	412233454686
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2017-08-07 10:35
---------------	------------------

MOT test number	821634998796
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2016-07-26 09:44
---------------	------------------

MOT test number	252753061836
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2015-08-12 09:36
---------------	------------------

MOT test number	900520094261
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2014-06-10 17:31
MOT test number	168001664176
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 A15FGS
Plate since	2019-09-29
Current registration	 A15FGS
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-04
Last registration	2023-09-28
Complete history	See info



Registration #1	2011-07-04	24 mi
Registration #2	2014-06-10	14.568 mi
Registration #3	2015-08-12	19.789 mi
Registration #4	2016-07-26	23.996 mi
Registration #5	2017-08-07	28.225 mi
Registration #6	2018-08-02	32.439 mi
Registration #7	2019-08-02	36.001 mi
Registration #8	2020-07-16	36.501 mi
Registration #9	2021-06-22	36.501 mi
Registration #10	2022-06-22	36.501 mi
Registration #11	2023-06-22	36.501 mi
Registration #12	2024-06-22	36.501 mi
Registration #13	2025-06-22	36.501 mi
Registration #14	2026-06-22	36.501 mi
Registration #15	2027-06-22	36.501 mi
Registration #16	2028-06-22	36.501 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1065 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1329501