





report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA S
Colour	Black
Year of manufacture	2010
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	235 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



WV60ZVT report date: 2024-03-29

MOT history

MOT expiry date	2024-07-10
MOT pass rate	92 %
	1.1
MOT passed	11
Failed MOT tests	1
Total advice items	19
Total items failed	1

MOT #12		2023-06-27 14:45
MOT test	number	921408104454
Result		✓ Passed
Next expiry date 2024-07-		2024-07-10
Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11	2022-06-15 12:19
MOT test	number 441887945248
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2021-06-16 08:35
MOT test number	919893607596
Result	✓ Passed
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

MOT #9	2020-07-11 17:59
MOT test number	413282037211
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2019-06-29 10:07 **MOT** test number 698364108368 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice • (emissions not tested due hybrid vehicle) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

2019-06-29 10:07 **MOT #7** 503339613656 **MOT** test number Result ★ Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Pass with rectification** Central Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** • (emissions not tested due hybrid vehicle)

MOT #6		2018-07-03 08:43
MOT test	number	286008913157
Result		✓ Passed
Advice	Central Front Brake slack adjuster advise adjustment (1.1.18 (a))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/12



Advice

WV60ZVT

report date: 2024-03-29

MOT #5	2017-06-12 08:36
MOT test number	529370520492
Result	✓ Passed
MOT #4	2016-06-10 08:06
MOT test number	541054431805
Result	✓ Passed
MOT #3	2015-06-19 16:30
MOT test number	417160975112
Result	✓ Passed
MOT #2	2014-10-16 13:41
MOT test number	185309784210
Result	✓ Passed

MOT #1	2013-10-23 13:26
MOT test number	129346793233
Result	✓ Passed

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	С
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

WV60ZVT

report date: 2024-03-29

UK UK

More info >

Owner history		
For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		DA
HARMAN AND AND AND AND AND AND AND AND AND A		

HARMAN CO.		

	More info	>
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		

CarCheck.co.uk page 9/12



WV60ZVT report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-28
Last registration	2023-06-27
Complete history	See info



Registration #1	2010-10-28	19 mi
Registration #2	2013-10-23	36.431 mi
Registration #3	2014-10-16	48.099 mi
Registration #4	2015-06-19	55.068 mi
Registration #5	2016-06-10	62.344 mi
Registration #6	2017-06-12	69.146 mi
Registration #7	2018-07-03	80.979 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		
Registration #12		1.77 m
		1.77 m

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



WV60ZVT report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1003488

CarCheck.co.uk page 12/12