





report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 SPORT DCI S/R W/V
Colour	Silver
Year of manufacture	2012
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	39.8 mpg
Consumption combined	35.8 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

		1
ᆮ	HLIV	-

Life y 1	
Date	2021-06-09
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-05	
MOT pass rate	73 %	
MOT passed	8	
Failed MOT tests	3	
Total advice items	29	
Total items failed	5	

MOT #11	2023-06-06 08:26
MOT test number	535119700263
Result	✓ Passed
Next expiry date	2024-06-05
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Emissions too clean to test	

MOT #10	2023-06-05 11:54
MOT test number	651352974710
Result	X Failed
Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Emissions too clean to test	
Advice Front Brake pad(s) wearing thin on 20% (1.1.13 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



Advice

GF12XBG

report date: 2024-03-28

MOT #9 2022-05-30 10:01 **MOT** test number 414539060987 Result **X** Failed **Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Emissions too clean to test Advice

MOT #8

MOT test number

790011547914

Result

Advice Wipers smearing

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Offside Front Tyre worn close to legal limit/worn on edge close to limit (5.2.3 (e))

MOT #7		2020-07-17 07:43
MOT test	number	894245834593
Result		✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Power steering rack has slight leak offside front rack gator damp	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice Power steering rack has slight leak offside front rack gator damp

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #5 2019-07-18 07:46 **MOT** test number 849485127723 Result ✓ Passed Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Offside Front Nail in tyre leaking **Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) **Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4

MOT test number

Result

Advice All four tyres cut in tread

MOT #3

MOT test number

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice
Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Front Brake pad(s) wearing thin on 1.5 mm (3.5.1g)

Advice
Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2015-07-20 15:39
MOT test number	709611905206
Result	√ Passed
Notice Nail in nearside rear tyre	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	5 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Own	≏r h	isto	rv

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		IAULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-12
Last registration	2023-06-06
Complete history	See info



Posistration #1	2012-07-12	26 mi
Registration #1	2012-07-12	20 1111
Registration #2	2015-07-20	15.537 mi
Registration #3	2016-07-07	20.743 mi
Registration #4	2017-06-21	23.427 mi
Registration #5	2018-06-20	25.989 mi
Registration #6	2019-07-18	30.868 mi
Registration #7	2020-07-17	35.862 mi
Registration #8		11.177 es
Registration #9		11.777 mi
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		0.77 sc

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Dimensions & weight

Width	1904 mm
Height	1955 mm
Length	5182 mm
Kerb weight	1926 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C050165

CarCheck.co.uk page 13/13