




report date: 2024-03-29

General information

Make	FORD
Model	GALAXY EDGE TDCI
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	189 g/km
CO2 label	J





## Internet history

### Entry 1

Date	2021-07-05
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-02
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	42
Total items failed	3

MOT #14 2023-10-03 11:23

MOT test number 730980743977

Result ✔ Passed

Next expiry date 2024-10-02

- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** O/s rear inner sill
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))



**MOT #13** 2022-09-21 16:09

**MOT test number** 835484367048

**Result** ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened ALL suspension components are corroded (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive Rear of engine (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2022-08-25 09:51

**MOT test number** 720403341790

**Result** ✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened ALL suspension components are corroded (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive Rear of engine (8.4.1 (a) (i))
- Fail** Rear Suspension arm pin or bush excessively worn Both trailing arm bushes (5.3.4 (a) (i))

**MOT #11** 2021-09-13 15:38

**MOT test number** 926995749758

**Result** ✓ Passed

**MOT #10** 2020-09-03 13:15

**MOT test number** 496191545028

**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



**MOT #9** 2019-08-20 08:05

**MOT test number** 410382144005

**Result** ✓ Passed

**MOT #8** 2018-09-05 11:07

**MOT test number** 809356737556

**Result** ✓ Passed

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2 m/m left (5.2.3 (e))

**MOT #7** 2017-09-02 10:09

**MOT test number** 182191416999

**Result** ✓ Passed

**Advice** Rear exhaust heat shield loose

**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Nearside & offside front tyres worn on edges & outer sidewalls cut

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tie bar/rod rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2016-09-05 07:18

**MOT test number** 320089361619

**Result** ✓ Passed



**MOT #5** 2016-02-04 10:38

**MOT test number** 973457063882

**Result** ✔ Passed

- Advice** Nearside Front brake disc lipped/corroded.
- Advice** Rear heat shield insecure.
- Advice** Offside Front brake disc lipped/corroded.

**MOT #4** 2015-03-05 08:43

**MOT test number** 685034265030

**Result** ✔ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nearside rear trailing arm rubber bush bonding splitting
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Front tyres wearing low in centre of tread
- Notice** Nail in nearside rear tyre and tread worn to 3mm

**MOT #3** 2015-02-27 12:02

**MOT test number** 416118855098

**Result** ✘ Failed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside rear trailing arm rubber bush bonding splitting
- Fail** Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Notice** Front tyres wearing low in centre of tread
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nail in nearside rear tyre and tread worn to 3mm
- Fail** Nearside Stop lamp not working (1.2.1b)



**MOT #2** 2014-02-26 12:37

**MOT test number** 939287454090

**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Notice** Timing belt due every 125,000 miles or every 10 years

**MOT #1** 2013-02-21 13:07

**MOT test number** 248342553086

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
2 October 2024

**Tax status** Valid until 1 March

**Days left** 306

**MOT expiry date** 2 October 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 10,000
<b>Auction value</b>	£ 10,000
<b>Average private trade value</b>	£ 10,000

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YL10YLL
Plate since	2010-03-29
Current registration	YL10YLL
Plate since	2010-03-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-01
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	15 mi
Registration #2	2013-02-21	55.356 mi
Registration #3	2014-02-26	74.407 mi
Registration #4	2015-02-27	89.166 mi
Registration #5	2015-03-05	89.166 mi
Registration #6	2016-02-04	100.157 mi
Registration #7	2016-09-05	100.826 mi
Registration #8	2017-09-02	107.340 mi
Registration #9	2018-09-02	113.854 mi
Registration #10	2019-09-02	120.368 mi
Registration #11	2020-09-02	126.882 mi
Registration #12	2021-09-02	133.396 mi
Registration #13	2022-09-02	139.910 mi
Registration #14	2023-09-02	146.424 mi
Registration #15	2023-10-03	147.938 mi
Registration #16	2023-10-03	150.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Max. allowed weight	2505 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	9E15196