



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2010
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	64.2 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2024-05-11
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	24
Total items failed	23

MOT #13	2023-05-12 14:20
MOT test number	175280128527
Result	✓ Passed
Next expiry date	2024-05-11

MOT #12	2021-05-07 11:11
MOT test number	421106715216
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))

**MOT #11**

2021-05-06 14:06

**MOT test number**

580365273500

**Result****✗ Failed**

- Fail** Emissions not tested (8.2.2.2 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s and o/s (1.1.14 (a) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Exhaust has a major leak of exhaust gases rear box missing (6.1.2 (a))

**MOT #10**

2020-01-17 16:30

**MOT test number**

413921298748

**Result****✓ Passed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Inner Exhaust mounting defective (6.1.2 (a))
- Advice** Spare tyre defective
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #9** 2019-01-15 11:13**MOT test number** 199417176818**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #8** 2019-01-14 16:22**MOT test number** 423934557046**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



<b>MOT #7</b>	2018-01-13 08:27
<b>MOT test number</b>	251142762541
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #6</b>	2017-01-14 11:49
<b>MOT test number</b>	261080179600
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2017-01-13 10:42
<b>MOT test number</b>	349822928191
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
<b>Fail</b>	Offside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Fail</b>	Nearside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Nearside Registration plate lamp not working (1.1.C.1d)

<b>MOT #4</b>	2015-11-19 11:47
<b>MOT test number</b>	463870619952
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Clutch pedal rubber is missing

<b>MOT #3</b>	2014-10-16 10:36
<b>MOT test number</b>	847309884203
<b>Result</b>	✓ Passed



MOT #22014-10-15 12:30

MOT test number458038184294

ResultX Failed

- Fail

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Offside Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail

Nearside Rear Registration plate lamp not working (1.1.C.1d)
- Fail

Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail

Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail

Offside Front Lower Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #12013-10-15 08:06

MOT test number657988383269

Result✓ Passed

- Notice

Offside front tyre tread 2mm



Tax & MOT check

✕  
Untaxed

Tax expired:  
24 May 2023

✓  
MOT

Expires:  
11 May 2024

Tax status	Expired at 24 May 2023
Days left	342 days too late
MOT expiry date	11 May 2024
Full MOT history	<a href="#">See MOT history</a>



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>YX11XX</b>
Plate since	2019-01-01
Current registration	 <b>YX11XX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-10-13
Last registration	2023-05-12
Complete history	<a href="#">See info</a>



Registration #1	2010-10-13	18 mi
Registration #2	2013-10-15	71.312 mi
Registration #3	2014-10-15	103.584 mi
Registration #4	2014-10-16	103.584 mi
Registration #5	2015-11-19	109.996 mi
Registration #6	2017-01-13	115.749 mi
Registration #7	2017-01-14	115.749 mi
Registration #8	2018-05-20	121.500 mi
Registration #9	2019-05-20	121.500 mi
Registration #10	2020-05-20	121.500 mi
Registration #11	2021-05-20	121.500 mi
Registration #12	2022-05-20	121.500 mi
Registration #13	2023-05-12	121.500 mi

More info >



Dimensions & weight

Width	1685 mm
Height	1801 mm
Length	4323 mm
Wheel base	2716 mm
Kerb weight	1252 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	2096072