





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BLUE DRIVE
Colour	Blue
Year of manufacture	2017
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.700 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	68.9 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2022-01-14

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-08-28	
Pictures	1	
Listing price	<u>View report</u>	



source: heycar.co.uk

CarCheck.co.uk page 2/11



EO67ULA report date: 2024-03-28

MOT history

MOT expiry date	2024-09-17
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5	2023-09-15 09:13
MOT test number	310166856417
Result	<b>✓</b> Passed
Next expiry date	2024-09-17

MOT #4		2022-09-02 14:10
MOT test	number	161052271016
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

2022-09-02 08:30 **MOT** #3 576449806065 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** 

MOT #2

MOT test number

624524194656

Result

Advice Tyre slightly damaged/cracking or perishing Both rear tyres showing age cracks (5.2.3 (d) (ii))

MOT #1		2020-09-18 09:20
MOT test	number	113742650492
Result		<b>✓</b> Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



EO67ULA report date: 2024-03-28

## Tax & MOT check





**Expires:** 17 September 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	17 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history			

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HYUNDAI had different number plates. factor science

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-15
Last registration	2023-09-15
Complete history	See info



Registration #1	2017-09-15	21 mi
Registration #2	2020-09-18	20.523 mi
Registration #3	2021-08-20	23.873 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

page 10/11 CarCheck.co.uk



EO67ULA report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4745 mm
Wheel base	2770 mm
Kerb weight	1610 kg
Max. allowed weight	2090 kg

# Additional information

		•
Fuel tank capacity	70	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

**Engine number** D4FDHU754350