



report date: 2024-03-29

General information

Make	MINI
Model	MINI COOPER S
Colour	Black
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-20
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #9	2023-08-15 15:26
MOT test number	707360914290
Result	✓ Passed
Next expiry date	2024-08-20
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8	2023-08-12 10:26
MOT test number	633895020374
Result	✗ Failed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Offside Rear Anti-roll bar linkage fractured Damaged due to broken spring (5.3.3 (b) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7	2022-08-19 08:46
MOT test number	535432500434
Result	✓ Passed

**MOT #6** 2021-08-18 10:53**MOT test number** 461966025041**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view cracked on passenger side (3.2 (a) (i))**MOT #5** 2020-08-21 10:47**MOT test number** 936589992536**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm tread depth (5.2.3 (e))**MOT #4** 2019-03-11 09:38**MOT test number** 206153128835**Result** ✓ Passed**MOT #3** 2018-05-25 11:15**MOT test number** 744079821882**Result** ✓ Passed**MOT #2** 2017-06-10 10:18**MOT test number** 115103566325**Result** ✓ Passed**MOT #1** 2016-06-13 09:47**MOT test number** 877437962445**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 August 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	20 August 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-06-14
Last registration	2023-08-15
Complete history	See info



Registration #1	2013-06-14	10 mi
Registration #2	2016-06-13	27.522 mi
Registration #3	2017-06-10	35.644 mi
Registration #4	2018-05-25	42.027 mi
Registration #5	2019-03-11	50.926 mi
Registration #6	2020-08-21	61.578 mi
Registration #7	2021-05-20	65.277 mi
Registration #8	2021-05-20	65.277 mi
Registration #9	2021-05-20	65.277 mi
Registration #10	2021-05-20	65.277 mi
Registration #11	2023-08-15	65.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Engine number	A079J479
---------------	----------