





report date: 2024-03-28

# General information

Make	AUDI
Model	A2 SE
Colour	Silver
Year of manufacture	2004
Top speed	107 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	74 BHP	
Max. torque	126 Nm at 3.800 rpm	
Engine capacity	1.390 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	34.5 mpg	
Consumption extra urban	60.1 mpg	
Consumption combined	47.1 mpg	
CO2 emission	144 g/km	
CO2 label	F	



CarCheck.co.uk page 1/14



# Internet history

### Entry 1

Date 2021-10-27

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-26
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	21
Total items failed	14

MOT #18	2023-07-20 15:54
MOT test number	882524475487
Result	<b>✓</b> Passed
Next expiry date	2024-07-26

MOT #17 2023-07-19 09:25

**MOT test number** 825287615828

Result

× Failed

**Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Forward bush (5.3.4 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #16	2022-07-27 07:58
MOT test number	664034550331
Result	<b>✓</b> Passed

MOT #15	2021-06-19 08:59
MOT test number	930614634550
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



Result

LT54LMX

report date: 2024-03-28

✓ Passed

**MOT #14** 2021-06-11 10:49 913684664421 **MOT** test number Result × Failed Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail Offside Front Headlamp insecure (4.1.1 (c)) Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail Brake lever has insufficient reserve travel (1.1.2 (a)) Fail

MOT #13

MOT test number

408785849050

Result

✓ Passed

MOT #12

2015-12-30 17:06

MOT test number

158006004266

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #11

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

 MOT #10
 2014-08-09 12:30

 MOT test number
 949061324279

 Result
 ✓ Passed

CarCheck.co.uk page 4/14



**MOT #9** 2014-08-06 17:47

**MOT test number** 678958314241

Result X Failed

**Fail** Registration plate lamp not working (1.1.C.1d)

**Fail** Nearside Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)

Fail Battery insecure (1.9.1)

**MOT #8** 2013-08-10 10:07

MOT test number 366692423401

**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #7 2012-08-15 11:19

MOT test number 579058822277

Result 

Passed

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Child seat fitted not allowing full inspection of adult belt

**Advice** Front Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 5/14



LT54LMX

report date: 2024-03-28

 MOT #6
 2012-08-15 11:19

 MOT test number
 645018922234

**Result** X Failed

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**Advice** Front Shock absorber has a light misting of oil (2.7.3)

**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2011-08-13 11:09

MOT test number 226115121225

Result \square Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)

MOT #4 2010-06-30 15:14

**MOT test number** 821491980187

**Result** ✓ Passed

MOT #3 2009-03-13 13:53

MOT test number 120112179400

Result X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



MOT #2

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14



### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	26 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



# Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-09-24
Last registration	2023-07-20
Complete history	See info



Registration #1	2004-09-24	12 mi
Registration #2	2007-08-30	17.263 mi
Registration #3	2009-03-13	33.666 mi
Registration #4	2010-06-30	46.143 mi
Registration #5	2011-08-13	57.056 mi
Registration #6	2012-08-15	66.856 mi
Registration #7	2013-08-10	79.923 mi
Registration #8	2014-08-06	91.435 mi
Registration #9	2014-08-09	91.435 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

CarCheck.co.uk page 13/14



# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1676 mm
Height	1550 mm
Length	3810 mm
Wheel base	2405 mm
Kerb weight	1380 kg

# Additional information

Fuel tank capacity	34
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	BBY 471565 page 14/14