



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D R-DESIGN
Colour	White
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G







Internet history

Entry 1

Date	2022-02-10
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-14
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	22
Total items failed	7

MOT #17	2023-12-15 09:00
MOT test number	423106807696
Result	✓ Passed
Next expiry date	2024-12-14

MOT #16	2023-12-12 11:21
MOT test number	256804577811
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases Exhaust silencer corroded through and leaking (6.1.2 (a))
Fail	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #15	2022-12-06 08:24
MOT test number	988086010112
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases Advise. exhaust rear silencer corroded through and has slight leak of exhaust gasses (6.1.2 (a))
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #14** 2021-12-04 18:53**MOT test number** 359588749307**Result** ✓ Passed**Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #13** 2020-12-09 15:42**MOT test number** 502606775376**Result** ✓ Passed**Advice** Exhaust minor leak middle box**Advice** Front n/s tyre worn edges**Advice** Brake pipes minor rust rear**MOT #12** 2019-11-28 13:32**MOT test number** 950267827628**Result** ✓ Passed**MOT #11** 2019-11-28 09:15**MOT test number** 432629206767**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #10** 2018-11-23 15:48**MOT test number** 945647777934**Result** ✓ Passed**MOT #9** 2017-11-29 14:01**MOT test number** 869696329448**Result** ✓ Passed

**MOT #8** 2017-11-28 15:56**MOT test number** 520079348912**Result** ✗ Failed**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2016-12-28 10:51**MOT test number** 623676326625**Result** ✓ Passed**MOT #6** 2016-01-04 14:00**MOT test number** 936603412479**Result** ✓ Passed**MOT #5** 2016-01-04 14:00**MOT test number** 725205094774**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #4** 2015-02-19 10:41**MOT test number** 577790155035**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2014-02-12 13:12**MOT test number** 829223144036**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-02-12 13:12**MOT test number** 647923944028**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-02-04 14:59**MOT test number** 946345333044**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
14 December 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 YD10YAH
Plate since	2019-09-28
Current registration	 YD10YAH
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-01
Last registration	2023-12-15
Complete history	See info



Registration #1	2010-03-01	14 mi
Registration #2	2013-02-04	26.957 mi
Registration #3	2014-02-12	37.398 mi
Registration #4	2015-02-19	47.186 mi
Registration #5	2016-01-04	59.154 mi
Registration #6	2016-01-04	59.154 mi
Registration #7	2016-12-28	79.338 mi
Registration #8	2017-11-28	91.907 mi
Registration #9	2017-11-29	91.907 mi
Registration #10	2018-05-29	91.907 mi
Registration #11	2018-05-29	91.907 mi
Registration #12	2018-05-29	91.907 mi
Registration #13	2018-05-29	91.907 mi
Registration #14	2018-05-29	91.907 mi
Registration #15	2018-05-29	91.907 mi
Registration #16	2018-05-29	91.907 mi
Registration #17	2018-05-29	91.907 mi
Registration #18	2018-05-29	91.907 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	746796