



report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Silver
Year of manufacture	2006
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M






Internet history

Entry 2

Date	2021-09-07
Pictures	29
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-09-06
Pictures	29
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-02-24
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	35
Total items failed	9

MOT #18 2022-01-25 15:46

MOT test number 720644148240

Result ✓ Passed

Next expiry date 2023-02-24

**Advice** Offside Rear Integral body structure is corroded but structural rigidity is not significantly reduced  
Seal Area Corroded (6.1.1 (c) (i))

**Advice** Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced  
Seal Area Corroded (6.1.1 (c) (i))

**Advice** Nearside Rear Integral body structure is corroded but structural rigidity is not significantly reduced  
Seal Area Corroded (6.1.1 (c) (i))

MOT #17 2021-02-25 11:24

MOT test number 397213221851

Result ✓ Passed

**Advice** Offside Front Inner Sill excessively corroded, not within a prescribed area.

MOT #16 2019-06-20 13:51

MOT test number 787294232334

Result ✓ Passed

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #15**

2019-06-05 09:30

**MOT test number**

779299685143

**Result****✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Exhaust clamp broken
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Both rear tyres starting to wear out of shape on tread
- Fail** Offside Rear Lower Suspension arm ball joint excessively worn Outer joint and dust cover deteriorated (5.3.4 (a) (i))

**MOT #14**

2018-06-21 09:37

**MOT test number**

915751144618

**Result****✓ Passed**

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2018-06-21 09:37

**MOT test number**

270870103174

**Result****✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



**MOT #12** 2017-04-19 09:05**MOT test number** 454320717146**Result** ✓ Passed**Advice** Offside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #11** 2016-05-09 15:02**MOT test number** 625024850998**Result** ✓ Passed**Advice** Nearside wiper blade split**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2016-05-09 10:38**MOT test number** 607159562847**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside wiper blade split**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2015-04-29 16:35**MOT test number** 917099015191**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Items removed from driver's view prior to test**MOT #8** 2015-04-29 16:35**MOT test number** 816339515120**Result** ✗ Failed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Items removed from driver's view prior to test**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2014-05-15 11:22**MOT test number** 155745634121**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #6** 2013-01-21 10:21**MOT test number** 466911723049**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #5** 2012-01-18 14:48**MOT test number** 175148512408**Result** ✓ Passed



<b>MOT #4</b>	2011-01-27 10:21
---------------	------------------

<b>MOT test number</b>	626097421090
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2010-04-14 16:09
---------------	------------------

<b>MOT test number</b>	231104100400
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2010-03-12 14:09
---------------	------------------

<b>MOT test number</b>	554551370023
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside rear brake juddering severely (3.7.A.5b)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

<b>MOT #1</b>	2009-02-27 10:33
---------------	------------------

<b>MOT test number</b>	541488259022
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✕  
Untaxed

Tax expired:  
1 May 2023

✕  
MOT

Expired:  
24 February 2023

Tax status	Expired at 1 May 2023
Days left	365 days too late
MOT expiry date	24 February 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>SK060TG</b>
Plate since	2019-03-29
Current registration	<b>SK060TG</b>
Plate since	2019-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2022-01-25
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	6 mi
Registration #2	2009-02-27	20.914 mi
Registration #3	2010-03-12	28.387 mi
Registration #4	2010-04-14	28.441 mi
Registration #5	2011-01-27	28.645 mi
Registration #6	2012-01-18	34.086 mi
Registration #7	2013-01-21	39.549 mi
Registration #8	2014-05-15	42.348 mi
Registration #9	2015-04-29	45.917 mi
Registration #10	2016-05-09	52.145 mi
Registration #11	2016-05-09	52.145 mi
Registration #12	2016-05-09	52.145 mi
Registration #13	2016-05-09	52.145 mi
Registration #14	2016-05-09	52.145 mi
Registration #15	2016-05-09	52.145 mi
Registration #16	2016-05-09	52.145 mi
Registration #17	2016-05-09	52.145 mi
Registration #18	2016-05-09	52.145 mi
Registration #19	2016-05-09	52.145 mi
Registration #20	2016-05-09	52.145 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	542328359FG