



YF02ZPM

report date: 2024-03-29

General information

Make	BMW
Model	Z3
Colour	Silver
Year of manufacture	2002
Gearbox	-

Engine & fuel consumption

Engine capacity	1.895 cc
Fuel type	Petrol
CO2 emission	189 g/km
CO2 label	J





## Internet history

### Entry 3


Date	2021-12-20
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

### Entry 2

Date	2021-08-03
Pictures	10
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)

### Entry 1

Date	2021-07-31
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-07-01
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	61
Total items failed	14

MOT #25 2023-06-19 08:15

MOT test number 716673015912

Result ✓ Passed

Next expiry date 2024-07-01

**Advice** REAR SPRINGS CORRODED

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #24 2022-06-21 11:58

MOT test number 797153041102

Result ✓ Passed

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** FUEL CAP SEAL CRACKED

MOT #23 2021-07-02 10:47

MOT test number 877381805568

Result ✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22**

2021-06-30 11:47

**MOT test number**

506141338964

**Result****✗ Failed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Front Exhaust has a major leak of exhaust gases section blowing. (6.1.2 (a))
- MAJOR** Front Exhaust system insecure exhaust hanger broken away. (6.1.2 (a))
- MAJOR** Offside Front Coil spring fractured or broken lower coil broken. (5.3.1 (b) (i))
- MAJOR** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Exhaust has a major leak of exhaust gases mid section blowing, (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #21**

2020-06-29 11:07

**MOT test number**

658007038993

**Result****✓ Passed****MOT #20**

2020-06-24 14:23

**MOT test number**

515079765517

**Result****✗ Failed**

- MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #19**

2019-03-14 14:14

**MOT test number**

531979183093

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18**

2018-03-21 13:33

**MOT test number**

561324128356

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #17**

2018-03-19 12:05

**MOT test number**

282111647527

**Result**

✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #16**

2017-03-21 16:04

**MOT test number**

828252811924

**Result**

✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake pipes greased**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #15**

2017-03-13 13:10

**MOT test number**

480801429080

**Result**

✗ Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Brake pipes greased**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #14**

2016-03-22 10:32

**MOT test number**

650688126936

**Result**

✓ Passed

**Advice** Brake pipe slightly corroded both main (3.6.B.2c)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front rear wishbone bushes (2.4.G.2)

**MOT #13**

2016-03-21 11:28

**MOT test number**

981595101939

**Result**

✗ Failed

**Fail** Centre Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Brake pipe excessively corroded both rear axle (3.6.B.2c)**Fail** Front Exhaust system not adequately supported (7.1.1)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both front rear wishbone bushes (2.4.G.2)**Advice** Brake pipe slightly corroded both main (3.6.B.2c)**MOT #12**

2015-03-16 13:15

**MOT test number**

595115475077

**Result**

✓ Passed

**Advice** Brake pipe slightly corroded (3.6.B.2c)**Notice** Oil leak**MOT #11**

2015-03-10 11:35

**MOT test number**

646399365027

**Result**

✗ Failed

**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Notice** Oil leak**MOT #10**

2014-02-26 11:56

**MOT test number**

325917754087

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2013-03-13 10:59**MOT test number** 759752573008**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-03-14 11:29**MOT test number** 198574272054**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-03-16 10:28**MOT test number** 307355871081**Result** ✓ Passed**MOT #6** 2010-03-18 11:16**MOT test number** 891847070084**Result** ✓ Passed**MOT #5** 2008-07-15 12:27**MOT test number** 841757698188**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside front tyre



**MOT #4** 2007-07-23 12:50**MOT test number** 751834607223**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Both rear tyres starting to crack
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2006-07-26 11:29**MOT test number** 641157806213**Result** ✓ Passed**MOT #2** 2006-07-26 10:42**MOT test number** 840047506286**Result** ✗ Failed

- Fail** Exhaust system not adequately supported (7.1.1)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #1** 2006-07-24 12:07**MOT test number** 793575206204**Result** ✗ Failed

- Fail** Exhaust system not adequately supported (7.1.1)
- Advice** Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
1 July 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	1 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2002-06-01
Last registration	2023-06-19
Complete history	<a href="#">See info</a>



Registration #1	2002-06-01	29 mi
Registration #2	2006-07-24	26.667 mi
Registration #3	2006-07-26	26.667 mi
Registration #4	2006-07-26	26.667 mi
Registration #5	2007-07-23	29.411 mi
Registration #6	2008-07-15	32.190 mi
Registration #7	2010-03-18	47.166 mi
Registration #8	2011-03-16	52.276 mi
Registration #9	2012-03-14	54.178 mi
Registration #10	2013-03-13	56.224 mi
Registration #11	2014-02-26	59.530 mi
Registration #12	2015-03-10	61.150 mi
Registration #13	2015-03-16	61.173 mi
Registration #14	2016-03-21	62.815 mi
Registration #15	2016-03-22	62.823 mi
Registration #16	2016-03-22	62.823 mi
Registration #17	2016-03-22	62.823 mi
Registration #18	2016-03-22	62.823 mi
Registration #19	2016-03-22	62.823 mi
Registration #20	2016-03-22	62.823 mi
Registration #21	2016-03-22	62.823 mi
Registration #22	2016-03-22	62.823 mi
Registration #23	2016-03-22	62.823 mi
Registration #24	2016-03-22	62.823 mi
Registration #25	2016-03-22	62.823 mi
Registration #26	2016-03-22	62.823 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Additional information

Engine number	00749965
---------------	----------