



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 E-HDI VTR PLUS NAV
Colour	Silver
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg
CO2 emission	120 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-20
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-01-06
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	32
Total items failed	5

## MOT #14 2023-12-18 14:01

MOT test number 839913042784

Result ✓ Passed

Next expiry date 2025-01-06

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

## MOT #13 2023-12-12 09:24

MOT test number 263765832493

Result ✗ Failed

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

## MOT #12 2022-12-09 14:17

MOT test number 741653309019

Result ✓ Passed

**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Power steering component has slight seepage from a component (2.1.5 (a))

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #11**

2022-01-07 12:42

**MOT test number**

276775763589

**Result**

✓ Passed

**MOT #10**

2021-02-06 11:18

**MOT test number**

918355370739

**Result**

✓ Passed

**Advice**

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Items removed from driver's view prior to test

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2021-02-06 09:24

**MOT test number**

302950725089

**Result**

✗ Failed

**Fail**

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice**

Items removed from driver's view prior to test

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #8** 2020-02-04 16:35**MOT test number** 430653270954**Result** ✓ Passed**MOT #7** 2019-01-23 11:56**MOT test number** 984000126169**Result** ✓ Passed**Advice** Advise n/s door mirror glass is cracked but others are ok advise to replace**MOT #6** 2018-02-13 09:56**MOT test number** 409323700110**Result** ✓ Passed**Advice** Advise n/s/r tyre tread is low and outer wall is cracked and perished advise to replace**Advice** Advise drivers wiper blade worn advise to replace**Advice** Advise n/s door mirror glass is cracked and damaged advise to replace others are ok**MOT #5** 2017-01-27 11:59**MOT test number** 662620972372**Result** ✓ Passed**Advice** Advise o/s/f tyre worn on inside edge and n/s/f on outside edge advise to replace**Advice** Advise front and rear brake pads are very low advise to replace**Advice** Advise n/s door mirror glass is damaged advise to replace

**MOT #4** 2016-01-28 13:15**MOT test number** 278089014492**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-01-30 16:43**MOT test number** 286810135091**Result** ✓ Passed**Notice** Advise new tyres been fitted to o/s n/s front**MOT #2** 2015-01-29 13:27**MOT test number** 999499725061**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2014-05-28 13:51**MOT test number** 155878244154**Result** ✓ Passed**Notice** Slight wear out with 3/4 tread breadth o/s/f tyre inside edge



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
6 January 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	125
<b>MOT expiry date</b>	6 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-05-31
Last registration	2023-12-18
Complete history	<a href="#">See info</a>



Registration #1	2011-05-31	28 mi
Registration #2	2014-05-28	27.031 mi
Registration #3	2015-01-29	33.531 mi
Registration #4	2015-01-30	33.539 mi
Registration #5	2016-01-28	43.479 mi
Registration #6	2017-01-27	50.419 mi
Registration #7	2018-02-13	56.210 mi
Registration #8	2019-01-23	59.161 mi
Registration #9	2019-05-29	59.277 mi
Registration #10	2019-05-29	59.277 mi
Registration #11	2019-05-29	59.277 mi
Registration #12	2019-05-29	59.277 mi
Registration #13	2019-05-29	59.277 mi
Registration #14	2019-05-29	59.277 mi
Registration #15	2019-05-29	59.277 mi
Registration #16	2019-05-29	59.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1458 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1525 kg
Max. allowed weight	2062 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	JBDJ3000975