



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 XSI 16V
Colour	Silver
Year of manufacture	2002
Top speed	122 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	41.5 mpg
CO2 emission	161 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-27
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-13
MOT pass rate	55 %
MOT passed	18
Failed MOT tests	15
Total advice items	94
Total items failed	40

MOT #33	2023-12-14 10:55
MOT test number	279454994805
Result	✓ Passed
Next expiry date	2024-12-13
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #32	2023-01-07 10:50
MOT test number	854502554709
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #31	2021-12-29 10:44
MOT test number	132435420707
Result	✓ Passed

**MOT #30**

2021-12-28 10:44

**MOT test number**

773577037718

**Result****✗ Failed****Fail** Stop lamp(s) not working nearside and offside (4.3.1 (a) (ii))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #29**

2021-01-25 15:06

**MOT test number**

519829762124

**Result****✓ Passed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #28**

2021-01-25 11:45

**MOT test number**

346286754995

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Near side head lamp intermittent**Fail** Nearside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MOT #27**

2019-07-24 15:01

**MOT test number**

113159839620

**Result**

✓ Passed

- Advice** Front brake discs in poor condition
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre is BALD ON INNER EDGE, and very close to wear bars [195/55/r15]85v (5.2.3 (e))
- Advice** Both rear tyres are cracking
- Advice** Exhaust has a minor leak of exhaust gases from front joints (6.1.2 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin pads very low (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge close to central wear bars (5.2.3 (e))
- Advice** Rear brake discs in very poor condition on inner faces

**MOT #26**

2018-07-13 09:23

**MOT test number**

847459429538

**Result**

✓ Passed

- Minor** Offside Front Windscreen wiper blade defective Fouling screen. (3.4 (b) (i))
- Advice** Rear wiper insecure.
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre inner edge worn , close to the legal limit.

**MOT #25**

2018-07-13 09:17

**MOT test number**

258517613305

**Result****✗ Failed**

- Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill panel. (6.2.2 (d) (i))
- Minor** Offside Front Windscreen wiper blade defective Fouling screen (3.4 (b) (i))
- Advice** Rear Wiper insecure.
- Advice** Rear Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))

**MOT #24**

2018-07-12 08:54

**MOT test number**

688163772707

**Result****✗ Failed**

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective Fouling screen (3.4 (b) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Outer Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Sill panel. (6.2.2 (d) (i))
- Fail** Central Front Exhaust silencer likely to become detached (8.1.1 (b) (ii))
- Advice** Rear Brake pad(s) wearing thin Both sides. (1.1.13 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded Marked in yellow. (1.1.11 (c))
- Advice** Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #23** 2017-07-13 14:29**MOT test number** 424288342702**Result** ✓ Passed**Advice** Offside Front Blade fouling on windscreen trim/moulding**Advice** Front coil spring corroded Both (2.4.C.1b)**MOT #22** 2017-07-13 08:34**MOT test number** 922511763224**Result** ✗ Failed**Advice** Offside Front Blade fouling on windscreen trim/moulding**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Central Front Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Central Front Exhaust clamp insecure/loose.**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Front coil spring corroded Both (2.4.C.1b)**MOT #21** 2016-06-28 15:31**MOT test number** 994177619081**Result** ✓ Passed**Advice** Oil leak**Advice** Rear number plate light both lense missing**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)

**MOT #20**

2016-06-28 08:39

**MOT test number**

695549667056

**Result****✗ Failed**

- Fail** Rear registration plate faded (6.3.1d)
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Oil leak
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both sides (3.5.1i)
- Advice** Rear number plate light both lense missing

**MOT #19**

2015-07-10 09:26

**MOT test number**

708581895173

**Result****✓ Passed**

- Notice** Both sides rear brake pads wearing low
- Notice** Nearside front position light LED,offside front normal
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Both sides front brake pads wearing low
- Advice** Rear registration plate faded but not likely to be misread (6.3.1d)
- Notice** Nearside front windscreen crack
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)





MOT #18 2015-07-10 09:26

MOT test number 289131495415

Result ✗ Failed

**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**Notice** Both sides front brake pads wearing low

**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Nearside front windscreen crack

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Both sides rear brake pads wearing low

**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)

**Notice** Nearside front position light LED,offside front normal

MOT #17 2014-07-15 09:32

MOT test number 766606094138

Result ✓ Passed

**Notice** ADVISE both rear number plate light lenses are missing

**Notice** Advise front brake disc worn and pitted

**Notice** Advise ENGINE MANAGEMENT LIGHT ON

**Notice** Advise rear seat base missing

**Notice** Advise rear brake pads are worn low



MOT #16	2014-07-15 09:32
MOT test number	318736594125
Result	✗ Failed
Notice	Advise rear brake pads are worn low
Notice	ADVISE both rear number plate light lenses are missing
Notice	Advise front brake disc worn and pitted
Notice	Advise ENGINE MANAGEMENT LIGHT ON
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)
Notice	Advise rear seat base missing

MOT #15	2013-07-12 16:12
MOT test number	616013693151
Result	✓ Passed
Notice	Rear seat base missing
Notice	Screen was bottle cap missing

**MOT #14**

2013-07-12 09:44

**MOT test number**

285753893129

**Result****✗ Failed**

- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Notice** Screen was bottle cap missing
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** O/s/f plus n/s/r plus o/s/r tyre tread depth on 3mm
- Fail** Stop lamp remains on when the brakes are released (1.2.1e)
- Fail** Offside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Notice** Rear seat base missing
- Fail** Nearside Front Headlamp aim too high (1.8)
- Notice** N/s/f tyre on the legal limit
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Nearside Rear Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**MOT #13**

2012-07-25 15:07

**MOT test number**

428167602273

**Result****✓ Passed****MOT #12**

2012-07-24 11:25

**MOT test number**

606986802229

**Result****✗ Failed**

- Fail** Rear rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #11** 2011-04-08 17:37**MOT test number** 158248691017**Result** ✓ Passed

- Notice** Advise front exhaust heavily corroded
- Notice** Advise crash damage to offside rear wing and bumper
- Notice** Advise nearside tyre on 3mm
- Notice** Advise crack in nearside front top screen

**MOT #10** 2011-03-31 12:25**MOT test number** 619320891063**Result** ✗ Failed

- Fail** Nearside Front Headlamp aim too low (1.8)
- Notice** Advise nearside tyre on 3mm
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Notice** Advise crash damage to offside rear wing and bumper
- Notice** Advise crack in nearside front top screen
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Notice** Advise front exhaust heavily corroded

**MOT #9** 2010-03-15 13:50**MOT test number** 360244970087**Result** ✓ Passed

**MOT #8** 2010-03-12 15:09**MOT test number** 804571170076**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Centre Rear fog lamp not working (1.3.2b)**Fail** Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Front brake pads and discs have worn thin.**Fail** Offside Registration plate lamp not working (1.1.5c)**MOT #7** 2009-03-07 12:10**MOT test number** 452116069082**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Crack in windscreen outside of wiper sweep**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2009-03-07 11:36**MOT test number** 211866169060**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.5c)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Crack in windscreen outside of wiper sweep



<b>MOT #5</b>	2008-02-21 13:45
---------------	------------------

<b>MOT test number</b>	793092858036
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2007-03-09 13:18
---------------	------------------

<b>MOT test number</b>	803718067059
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2007-03-05 16:01
---------------	------------------

<b>MOT test number</b>	982164567011
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
-------------	---

<b>MOT #2</b>	2006-03-13 16:30
---------------	------------------

<b>MOT test number</b>	411215176008
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2006-03-04 11:08
---------------	------------------

<b>MOT test number</b>	531933866026
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Fail</b>	Offside Front Lower Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
-------------	---

<b>Fail</b>	Nearside Front Headlamp not working on dipped beam (1.7.5a)
-------------	---



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
13 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	13 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KE02FRP
Plate since	2019-09-29
Current registration	KE02FRP
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	33
First mileage registration	2002-03-01
Last registration	2023-12-14
Complete history	<a href="#">See info</a>



Registration #1	2002-03-01	8 mi
Registration #2	2006-03-04	36.903 mi
Registration #3	2006-03-13	36.903 mi
Registration #4	2007-03-05	45.656 mi
Registration #5	2007-03-09	45.738 mi
Registration #6	2008-02-21	52.650 mi
Registration #7	2009-03-07	63.273 mi
Registration #8	2009-03-07	63.273 mi
Registration #9	2010-03-12	79.747 mi
Registration #10	2010-03-15	79.748 mi
Registration #11	2011-03-31	91.331 mi
Registration #12	2011-04-08	91.354 mi
Registration #13	2012-07-24	93.083 mi
Registration #14	2012-07-25	93.083 mi
Registration #15	2013-07-12	99.326 mi
Registration #16	2013-07-12	99.326 mi
Registration #17	2014-07-15	109.811 mi
Registration #18	2015-05-20	121.277 mi
Registration #19	2015-05-20	121.277 mi
Registration #20	2015-05-20	121.277 mi
Registration #21	2015-05-20	121.277 mi
Registration #22	2015-05-20	121.277 mi
Registration #23	2015-05-20	121.277 mi
Registration #24	2015-05-20	121.277 mi
Registration #25	2015-05-20	121.277 mi
Registration #26	2015-05-20	121.277 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442
Registration #33	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1432 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1088 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	FX2F1559692