





report date: 2024-03-28

#### General information

Make	FIAT
Model	500X MULTIAIR POP STAR
Colour	Blue
Year of manufacture	2016
Top speed	118 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	140 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28


# Internet history

#### Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



PF66LHX report date: 2024-03-28

MOT history

MOT expiry date	2024-10-14
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	2

MOT #6		2023-10-13 12:24
MOT test	number	229361655209
Result		✓ Passed
Next expi	ry date	2024-10-14
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5	2022-10-15 07:54
MOT test	number 561236762763
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

MOT #4	2021-10-12 08:29
MOT test number	337941794955
Result	<b>✓</b> Passed
MOT #2	2020 10 14 11 10

MOT #3	2020-10-14 11:19
MOT test number	912879845205
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2020-03-31 15:48

**MOT test number** 658702381116

**Result** ✓ Passed

MOT #1 2020-03-31 12:16

**MOT test number** 526546058719

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge 215/55/17 (5.2.3 (e))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Offside Rear Nail in tyre

Advice No oil on dipstick add 1ltr 5/30 oil to allow emission check

Advice Offside Front Tyre worn close to legal limit/worn on edge 215/55/17 (5.2.3 (e))

**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	14 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

o mice mistory	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
***************************************	
********	
*************	
	More info >
Plate changes  See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



PF66LHX report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
011.1.5	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-10-28
Last registration	2023-10-13
Complete history	See info



Registration #1	2016-10-28	16 mi
Registration #2	2020-03-31	20.764 mi
Registration #3	2020-03-31	20.764 mi
Registration #4	2020-10-14	22.046 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



PF66LHX report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1796 mm
Height	1600 mm
Length	4248 mm
Wheel base	2570 mm
Kerb weight	1320 kg
Max. allowed weight	1875 kg

### Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine number2166075