





report date: 2024-03-29

General information

Make	FORD
Model	FIESTA ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
CO2 emission	133 g/km
CO2 label	Е



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date 2021-07-14

Pictures 48

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-08

Pictures 47

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-08
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	34
Total items failed	7

MOT #14		2023-07-07 13:34
MOT test	number	313274988788
Result		✓ Passed
Next expi	ry date	2024-07-08
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice	Rear axle bushes deteriorated but not excessive	

CarCheck.co.uk page 3/14



Fail

FN10HUK

report date: 2024-03-29

MOT #13 2023-07-07 08:51 947603675054 **MOT** test number Result × Failed Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Rear axle bushes deteriorated but not excessive Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) **Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d)) Fail Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #12	2022-06-14 08:56
MOT test	number 835038940718
Result	✓ Passed
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #11		2021 06 22 00 14
MOT #11	num box	2021-06-22 09:14
110111001	number	
Result		✓ Passed
Advice	Front Coil spring corroded both (5.3.1 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.3	1.14 (a) (ii))
Advice	O s f steel wheel slight damaged from inner	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10		2020-07-09 09:20
MOT test	number	346472222035
Result		✓ Passed
Advice	Coil spring corroded both front (5.3.1 (b) (i))	
Advice	Offside Front steel wheel slight damaged from inner	
Advice	Brake disc worn, but not excessively both front inner facing (1.1.14 (a) (i))	
Advice	Coil spring corroded both rears (5.3.1 (b) (i))	

MOT #9		2019-07-17 09:25
MOT test	number	323737984259
Result		✓ Passed
Advice	Both front coil springs slight corroded	
Advice	Both rear coil springs slight corroded	
Advice	Offside Front inner wheel rim damaged	
Advice	Front wipers slight smearing	

MOT #8		2018-07-17 12:29
MOT test	number	934015286808
Result		✓ Passed
Advice	Child Seat fitted not allowing full inspection of adult belt o/s/r and n/s/f seat	
Advice	Both rear coil spring corroded at bottom	
Advice	Front discs inner facing corroded	
Advice	Service brake fluctuating, but not excessively both front (1.2.1 (e))	

MOT #7	2017-07-07 10:10
MOT test number	469517252649
Result	✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

663019890277

Result

Advice Offside Rear Tyre worn close to the legal limit perished / split (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit worn on inside edge (4.1.E.1)

MOT test number

Result

Advice Nearside Rear tyre cracking in tread

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear tyre cracking in tread

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear tyre cracking in tread

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

Advice Nearside Rear tyre cracking in tread

 MOT #3
 2015-04-10 12:02

 MOT test number
 858310105199

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2	2014-04-11 11:56
MOT test number	218671104107
Result	✓ Passed
MOT #1	2013-04-10 14:27
MOT test number	639550103178
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	8 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

e when mistery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-15
Last registration	2023-07-07
Complete history	See info



Registration #1	2010-04-15	20 mi
Registration #2	2013-04-10	23.450 mi
Registration #3	2014-04-11	27.313 mi
Registration #4	2015-04-10	30.995 mi
Registration #5	2016-06-17	45.868 mi
Registration #6	2016-06-17	45.868 mi
Registration #7	2017-07-06	40.707 mi
Registration #8	2017-07-07	40.712 mi
Registration #9	2018-07-17	45.119 mi
Registration #10		11.117 es
Registration #11		11.177 es
Registration #12		11.117 es
Registration #13		11.777 es
Registration #14		
Registration #15		11.777 mi
Registration #15 Registration #16		11.777 mg

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1722 mm
Height	1433 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1109 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pag	ge 14/14