



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-01-07
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2024-05-25
MOT pass rate	85 %
MOT passed	22
Failed MOT tests	4
Total advice items	14
Total items failed	11

MOT #26	2023-05-04 11:54
MOT test number	803763057319
Result	✓ Passed
Next expiry date	2024-05-25
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #25	2023-05-04 10:37
MOT test number	327168412842
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #24	2022-05-26 11:48
MOT test number	617231255321
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #23**

2022-05-18 09:53

MOT test number

280558669070

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Advice** Coolant leak 4ltrs add (just water)**Advice** Offside Front Suspension rod ball joint has slight play drop link (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin inner pads (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken broken lower coils (5.3.1 (b) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Coil spring fractured or broken broken lower coils (5.3.1 (b) (i))**MOT #22**

2022-01-06 18:00

MOT test number

578091215406

Result**✓ Passed****MOT #21**

2021-05-04 10:46

MOT test number

532997740176

Result**✓ Passed****MOT #20**

2020-11-05 11:05

MOT test number

402648925945

Result**✓ Passed****Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #19** 2019-11-02 14:00**MOT test number** 726428976078**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #18** 2019-05-10 10:38**MOT test number** 263785204636**Result** ✓ Passed**MOT #17** 2019-05-10 10:38**MOT test number** 253359197808**Result** ✗ Failed**Pass with rectification** Offside Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #16** 2018-10-24 09:47**MOT test number** 759961154092**Result** ✓ Passed**MOT #15** 2018-09-10 09:26**MOT test number** 575004306446**Result** ✓ Passed**MOT #14** 2018-03-17 11:26**MOT test number** 231230184064**Result** ✓ Passed



MOT #13	2017-09-22 09:27
----------------	------------------

MOT test number	655685588091
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2017-03-22 10:21
----------------	------------------

MOT test number	619787681801
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2016-09-28 09:09
----------------	------------------

MOT test number	248463461402
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2016-03-29 14:30
----------------	------------------

MOT test number	511736724611
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear parking brake slightly low
---------------	---

MOT #9	2015-10-03 09:20
---------------	------------------

MOT test number	677356253574
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2015-04-07 14:12
---------------	------------------

MOT test number	429677795004
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2014-10-08 11:06
---------------	------------------

MOT test number	368721784479
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #6** 2014-04-11 15:54**MOT test number** 445491404155**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-10-16 10:19**MOT test number** 759299783258**Result** ✓ Passed**MOT #4** 2013-04-24 08:49**MOT test number** 318904313116**Result** ✓ Passed**MOT #3** 2012-10-18 16:32**MOT test number** 378302092293**Result** ✓ Passed**MOT #2** 2012-10-18 16:32**MOT test number** 307552892238**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #1** 2012-07-02 13:53**MOT test number** 298754982129**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
25 May 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2011-07-07
Last registration	2023-05-04
Complete history	See info



Registration #1	2011-07-07	11 mi
Registration #2	2012-07-02	27.980 mi
Registration #3	2012-10-18	39.080 mi
Registration #4	2013-04-24	60.371 mi
Registration #5	2013-10-16	78.013 mi
Registration #6	2014-04-11	94.923 mi
Registration #7	2014-10-08	116.769 mi
Registration #8	2015-04-07	139.714 mi
Registration #9	2015-10-03	158.490 mi
Registration #10	2016-03-29	169.932 mi
Registration #11	2016-09-28	178.913 mi
Registration #12	2017-03-22	185.402 mi
Registration #13	2017-09-22	189.660 mi
Registration #14	2018-03-17	196.087 mi
Registration #15	2018-09-17	202.514 mi
Registration #16	2019-03-14	208.941 mi
Registration #17	2019-09-11	215.368 mi
Registration #18	2020-03-09	221.795 mi
Registration #19	2020-09-07	228.222 mi
Registration #20	2021-03-05	234.649 mi
Registration #21	2021-09-02	241.076 mi
Registration #22	2022-03-01	247.503 mi
Registration #23	2022-08-29	253.930 mi
Registration #24	2023-02-26	260.357 mi
Registration #25	2023-08-24	266.784 mi
Registration #26	2024-02-21	273.211 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBB838423