



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO LX 600 D P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	71 BHP
Max. torque	125 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #18	2020-11-23 13:02
MOT test number	526168714987
Result	✓ Passed
Next expiry date	2021-11-22
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Minor	Nearside Rear fog lamp lens defective which has no effect on emitted light lens slightly damaged (4.5.1 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

MOT #17	2019-11-04 12:02
MOT test number	466981817068
Result	✓ Passed

MOT #16	2018-11-07 10:25
MOT test number	637636366907
Result	✓ Passed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2018-11-07 10:25
MOT test number	893482864426
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14** 2017-10-30 17:06**MOT test number** 371480836068**Result** ✓ Passed**MOT #13** 2016-11-08 11:34**MOT test number** 886427244331**Result** ✓ Passed**Advice** O/s/r & n/s/r wheel bearings slight noise not excessive**MOT #12** 2015-11-09 17:05**MOT test number** 964290617646**Result** ✓ Passed**MOT #11** 2014-11-06 17:05**MOT test number** 168220114353**Result** ✓ Passed**Notice** N/s/f tyre worn on outer edge**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Both front wishbone rear bushes worn**MOT #10** 2013-11-06 11:32**MOT test number** 657420913379**Result** ✓ Passed**MOT #9** 2012-11-06 15:11**MOT test number** 916281712306**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2011-10-29 08:31**MOT test number** 808522101380**Result** ✓ Passed**MOT #7** 2010-11-02 16:05**MOT test number** 432506600361**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2010-11-02 09:19**MOT test number** 402526300419**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Tyre size 175/65 r14c 90/88t**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Clutch cable rubbing on n/s/front drive shaft**MOT #5** 2009-11-10 12:02**MOT test number** 661534519323**Result** ✓ Passed**Notice** Tyre size 175/65r 14c**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2008-11-04 11:28**MOT test number** 463819308475**Result** ✓ Passed**Notice** Tyre size 175/65 r14c**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-11-07 09:53**MOT test number** 793381517369**Result** ✓ Passed**Notice** Nail in offside front tyre**MOT #2** 2007-11-07 09:53**MOT test number** 463551617361**Result** ✗ Failed**Notice** Nail in offside front tyre**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #1** 2006-11-07 10:51**MOT test number** 552411416315**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	BD53YZR
Plate since	2019-03-29
Current registration	BD53YZR
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2003-11-07
Last registration	2020-11-23
Complete history	See info



Registration #1	2003-11-07	15 mi
Registration #2	2006-11-07	32.382 mi
Registration #3	2008-11-04	49.171 mi
Registration #4	2009-11-10	59.805 mi
Registration #5	2010-11-02	70.520 mi
Registration #6	2010-11-02	79.520 mi
Registration #7	2011-10-29	77.125 mi
Registration #8	2012-11-06	85.633 mi
Registration #9	2013-11-06	92.195 mi
Registration #10	2014-11-06	99.777 mi
Registration #11	2015-11-06	107.359 mi
Registration #12	2016-11-06	114.941 mi
Registration #13	2017-11-06	122.523 mi
Registration #14	2018-11-06	130.105 mi
Registration #15	2019-11-06	137.687 mi
Registration #16	2020-11-23	145.269 mi
Registration #17	2021-11-23	152.851 mi

More info >



Dimensions & weight

Width	1724 mm
Height	1819 mm
Length	4137 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	4
Engine number	DXFR6007519