



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	MATRIX COMFORT
Colour	Black
Year of manufacture	2008
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	141 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H







Internet history

Entry 2


Date	2022-01-21
Pictures	42
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-03
Pictures	38
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-09
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	21
Total items failed	15

MOT #18	2024-01-10 18:09
MOT test number	562335216557
Result	✓ Passed
Next expiry date	2025-01-09
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2024-01-10 13:02
MOT test number	395623249139
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Front Tyre tread depth below requirements of 1.6mm Both (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Brake pipe excessively corroded (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Front Direction indicator not working (4.4.1 (a) (ii))

**MOT #16**

2023-01-04 18:40

**MOT test number**

639002004754

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement  
Wishbone Bush (5.3.4 (a) (i))

**MOT #15**

2021-12-17 16:18

**MOT test number**

226510461267

**Result**

✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material Both main brake pipes (1.1.11 (c))
- Advice** Front Tyre worn close to legal limit/worn on edge Both wearing from inner edges (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))
- Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing From inside (5.2.3 (d) (ii))

**MOT #14**

2021-12-06 17:50

**MOT test number**

620587908795

**Result****✗ Failed**

- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Front Suspension arm corroded but not seriously weakened Both (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing From inside (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Outer (6.1.7 (g) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material Both main brake pipes (1.1.11 (c))
- Fail** Exhaust has a major leak of exhaust gases Front exhaust flexi (6.1.2 (a))
- Advice** Front Tyre worn close to legal limit/worn on edge Both wearing from inner edges (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Front Brake pipe corroded, covered in grease or other material Both (1.1.11 (c))

**MOT #13**

2020-11-23 13:00

**MOT test number**

706121054617

**Result****✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake pipe corroded, covered in grease or other material to rear both (1.1.11 (c))

**MOT #12** 2020-11-23 11:22**MOT test number** 146790589634**Result** ✗ Failed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Brake pipe corroded, covered in grease or other material to rear both (1.1.11 (c))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #11** 2019-11-27 15:17**MOT test number** 614422301373**Result** ✓ Passed**MOT #10** 2019-11-27 15:17**MOT test number** 615517206038**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2019-05-03 07:12**MOT test number** 100417363661**Result** ✓ Passed**MOT #8** 2018-05-14 06:29**MOT test number** 161723467629**Result** ✓ Passed



<b>MOT #7</b>	2017-05-22 06:48
<b>MOT test number</b>	169850206067
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2016-05-09 09:55
<b>MOT test number</b>	729484887917
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2015-05-08 09:04
<b>MOT test number</b>	879948125188
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2014-05-07 10:03
<b>MOT test number</b>	118237024121
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2013-05-13 08:20
<b>MOT test number</b>	229943233443
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2012-05-31 17:48
<b>MOT test number</b>	237072952168
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2011-07-12 13:13
<b>MOT test number</b>	525703691192
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
9 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	9 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-28
Last registration	2024-01-10
Complete history	<a href="#">See info</a>



Registration #1	2008-07-28	22 mi
Registration #2	2011-07-12	13.326 mi
Registration #3	2012-05-31	17.926 mi
Registration #4	2013-05-13	24.303 mi
Registration #5	2014-05-07	30.844 mi
Registration #6	2015-05-08	38.132 mi
Registration #7	2016-05-09	45.360 mi
Registration #8	2017-05-22	51.045 mi
Registration #9	2018-05-14	55.111 mi
Registration #10	2019-05-03	58.886 mi
Registration #11	2019-11-27	61.026 mi
Registration #12	2020-05-20	61.337 mi
Registration #13	2020-05-20	61.337 mi
Registration #14	2020-05-20	61.337 mi
Registration #15	2020-05-20	61.337 mi
Registration #16	2020-05-20	61.337 mi
Registration #17	2020-05-20	61.337 mi
Registration #18	2020-05-20	61.337 mi
Registration #19	2020-05-20	61.337 mi
Registration #20	2020-05-20	61.337 mi
Registration #21	2020-05-20	61.337 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1740 mm
Height	1685 mm
Length	4050 mm
Wheel base	2600 mm
Kerb weight	1327 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	G4ED7T024652