



GXI5KFG

report date: 2024-03-29

General information

Make	LEXUS
Model	IS 300H F SPORT
Colour	Blue
Year of manufacture	2015
Top speed	125 mph
0 - 60 mph	8.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	178 BHP
Max. torque	221 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	57.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-10
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT expiry date	2024-07-18
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #9	2023-07-18 15:02
MOT test number	700552357341
Result	✓ Passed
Next expiry date	2024-07-18

MOT #8	2022-07-08 08:13
MOT test number	378081775156
Result	✓ Passed

MOT #7	2022-07-08 08:13
MOT test number	336413151418
Result	✗ Failed
Pass with rectification Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	

MOT #6	2021-07-19 12:59
MOT test number	420788938533
Result	✓ Passed

MOT #5	2021-03-02 10:36
MOT test number	691465995819
Result	✓ Passed

**MOT #4** 2020-02-26 10:55**MOT test number** 615355978450**Result** ✓ Passed**MOT #3** 2019-03-15 15:23**MOT test number** 152334333966**Result** ✓ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2018-02-23 14:17**MOT test number** 116537140482**Result** ✓ Passed

- Advice** Under-trays fitted obscuring some underside components
- Advice** Engine covers fitted obscuring some components in the engine bay

MOT #1 2018-02-23 11:55**MOT test number** 953567401813**Result** ✗ Failed

- Advice** Engine covers fitted obscuring some components in the engine bay
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-01
Last registration	2023-07-18
Complete history	See info



Registration #1	2015-03-01	11 mi
Registration #2	2018-02-23	22.187 mi
Registration #3	2018-02-23	22.187 mi
Registration #4	2019-03-15	31.329 mi
Registration #5	2020-02-26	42.939 mi
Registration #6	2021-03-02	45.332 mi
Registration #7	2023-07-18	45.332 mi
Registration #8	2023-07-18	45.332 mi
Registration #9	2023-07-18	45.332 mi
Registration #10	2023-07-18	45.332 mi
Registration #11	2023-07-18	45.332 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1430 mm
Length	4665 mm
Wheel base	2800 mm
Kerb weight	1720 kg
Max. allowed weight	2145 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2AR1223234