



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 ALLURE COUPE CABRIOLET
Colour	Black
Year of manufacture	2007
Top speed	119 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	I





MOT history

MOT expiry date	2024-07-13
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	54
Total items failed	15

MOT #22	2023-07-14 13:24
MOT test number	657299010894
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin BOTH (1.1.13 (a) (ii))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Front Brake pad(s) wearing thin BOTH (1.1.13 (a) (ii))

MOT #21	2022-04-14 15:00
MOT test number	740358812123
Result	✓ Passed
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2022-04-04 12:53

**MOT test number**

722099818910

**Result****✗ Failed**

- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Minor** Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #19**

2021-04-14 10:28

**MOT test number**

446762486816

**Result****✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #18**

2021-04-08 14:38

**MOT test number**

520239344114

**Result**

✗ Failed

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Rear Exhaust system insecure (6.1.2 (a))**Fail** Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #17**

2020-03-25 10:06

**MOT test number**

877984257089

**Result**

✓ Passed

**MOT #16**

2019-03-18 10:26

**MOT test number**

314924240441

**Result**

✓ Passed

**Advice** Play in steering rack inner joint(s) both**Advice** Both front outer cv boot clips broken**MOT #15**

2018-04-06 12:39

**MOT test number**

117176508736

**Result**

✓ Passed

**Advice** Offside Play in steering rack inner joint(s)**Advice** Offside Rear tyre cracked around sidewall and tread

**MOT #14** 2018-04-06 12:39**MOT test number** 837127995360**Result** ✗ Failed**Advice** Offside Rear tyre cracked around sidewall and tread**Advice** Offside Play in steering rack inner joint(s)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #13** 2017-03-08 10:04**MOT test number** 180415982110**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit Void of tread on inner band (4.1.E.1)**Advice** Offside Front Play in steering rack inner joint(s)**MOT #12** 2016-03-03 11:02**MOT test number** 324304759511**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside slight play in steering rack inner joint**MOT #11** 2016-03-01 11:04**MOT test number** 163841798199**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside slight play in steering rack inner joint**Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2015-02-16 13:25**MOT test number** 165877545064**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #9** 2015-02-16 10:05**MOT test number** 305097445063**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Play in steering rack inner joint(s)**MOT #8** 2014-02-08 14:19**MOT test number** 289669134048**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2013-03-08 13:39**MOT test number** 128177163457**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Play in steering rack inner joint(s)**MOT #6** 2013-03-08 13:21**MOT test number** 707977463022**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Play in steering rack inner joint(s)

**MOT #5** 2012-03-10 14:56**MOT test number** 929960472013**Result** ✓ Passed**Notice** Slight play in both sides steering rack end joints**Notice** Offside rear tyre worn to 1.6mm across tread and bald on inner edge**MOT #4** 2011-02-23 12:42**MOT test number** 796654751040**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-02-23 12:42**MOT test number** 126854251457**Result** ✗ Failed**Notice** Nail in offside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-02-03 14:21**MOT test number** 182974430406**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-02-03 14:21
MOT test number	111934730047
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-06
Last registration	2023-07-14
Complete history	<a href="#">See info</a>



Registration #1	2007-06-06	10 mi
Registration #2	2010-02-03	34.043 mi
Registration #3	2011-02-23	45.556 mi
Registration #4	2012-03-10	52.593 mi
Registration #5	2013-03-08	56.046 mi
Registration #6	2013-03-08	56.046 mi
Registration #7	2014-02-08	58.950 mi
Registration #8	2015-02-16	61.975 mi
Registration #9	2015-02-16	21.404 mi
Registration #10	2016-03-01	65.919 mi
Registration #11	2016-03-03	65.919 mi
Registration #12	2016-03-03	65.919 mi
Registration #13	2016-03-03	65.919 mi
Registration #14	2016-03-03	65.919 mi
Registration #15	2016-03-03	65.919 mi
Registration #16	2016-03-03	65.919 mi
Registration #17	2016-03-03	65.919 mi
Registration #18	2016-03-03	65.919 mi
Registration #19	2016-03-03	65.919 mi
Registration #20	2016-03-03	65.919 mi
Registration #21	2016-03-03	65.919 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1528 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FX7U3288774