



RE60XHB

report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER D
Colour	Silver
Year of manufacture	2011
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





MOT history

MOT expiry date	2024-11-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	5

MOT #16	2023-11-22 12:16
MOT test number	566023934121
Result	✓ Passed
Next expiry date	2024-11-21
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	TPMS lamp illuminated on dash.
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2022-11-22 13:34
MOT test number	855469642690
Result	✓ Passed

MOT #14	2022-07-28 12:11
MOT test number	960349950869
Result	✓ Passed

MOT #13	2022-02-09 14:18
MOT test number	639306505629
Result	✓ Passed

**MOT #12**

2020-07-02 09:50

MOT test number

243273409846

Result

✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2020-07-02 09:50

MOT test number

686889936155

Result

✗ Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10**

2019-06-25 14:50

MOT test number

500139082246

Result

✓ Passed

MOT #9

2019-06-25 11:51

MOT test number

838645408426

Result

✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #8** 2018-06-27 16:04**MOT test number** 895810713048**Result** ✓ Passed

Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2017-06-19 11:45**MOT test number** 453507479262**Result** ✓ Passed**MOT #6** 2016-06-15 14:42**MOT test number** 965218100316**Result** ✓ Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #5 2016-06-15 13:33**MOT test number** 754114831701**Result** ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Rear Tyre has ply or cords exposed both cracking on sidewalls (4.1.D.1b)

Advice Front Inner Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-06-29 10:00**MOT test number** 276870285111**Result** ✓ Passed**Notice** Rear tyres cracking on sidewalls**MOT #3** 2014-07-03 14:24**MOT test number** 215554184137**Result** ✓ Passed**MOT #2** 2013-12-16 13:54**MOT test number** 956710053363**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Both front tyres starting to get low**MOT #1** 2013-12-16 13:54**MOT test number** 676820753309**Result** ✗ Failed**Notice** Both front tyres starting to get low**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
21 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	RE60XHB
Plate since	2019-09-29
Current registration	RE60XHB
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-01-05
Last registration	2023-11-22
Complete history	See info



Registration #1	2011-01-05	22 mi
Registration #2	2013-12-16	30.839 mi
Registration #3	2014-07-03	35.572 mi
Registration #4	2015-06-29	42.195 mi
Registration #5	2016-06-15	49.180 mi
Registration #6	2016-06-15	49.180 mi
Registration #7	2017-06-19	56.651 mi
Registration #8	2018-06-27	64.450 mi
Registration #9	2019-06-27	72.249 mi
Registration #10	2020-06-27	80.048 mi
Registration #11	2021-06-27	87.847 mi
Registration #12	2022-06-27	95.646 mi
Registration #13	2023-06-27	103.445 mi
Registration #14	2023-06-27	103.445 mi
Registration #15	2023-06-27	103.445 mi
Registration #16	2023-06-27	103.445 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70757967