





report date: 2024-03-29

### General information

Make	CITROEN
Model	DISPATCH XL 1200 ENTERPRISE BLUEHDI
Colour	Black
Year of manufacture	2017
Top speed	90 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	94 BHP
Max. torque	210 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	52.3 mpg
Consumption combined	50.4 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2021-11-11


Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2024-11-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	11
Total items failed	8

MOT #7		2023-11-13 16:54
MOT test	number	224697248956
Result		✓ Passed
Next expi	ry date	2024-11-16
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT #6** 2023-11-10 11:54

**MOT test number** 123100068456

Result X Failed

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #5 2022-11-04 14:42

MOT test number 458551503787

Result 

Passed

Advice Nearside n/s sill slightly damaged

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #4 2021-11-17 17:07

MOT test number 158489107847

**Result** ✓ Passed

MOT #3 2020-12-23 13:27

**MOT test number** 612908243962

**Result** ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #1

MOT test number

762210520153

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	16 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

<b>^</b>		histor	-
- ( ) ( )	vnor	nictor	٦.
$\smile$	VIICI	пизсоп	·v

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		1
********		
***************************************		
***************************************		
***************************************		
THE PERSON NAMED IN COLUMN TO THE PE		
	More info >	
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	OK STATE OF THE ST	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-06-23
Last registration	2023-11-13
Complete history	See info



Registration #1	2017-06-23	9 mi
Registration #2	2020-12-23	65.318 mi
Registration #3	2020-12-23	65.318 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 11/12



# Dimensions & weight

Width	2204 mm
Height	1940 mm
Length	5309 mm
Kerb weight	1574 kg
Max. allowed weight	2830 kg

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBHJ0026736

CarCheck.co.uk page 12/12