



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D SE
Colour	Blue
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-03-20
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-02
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	27
Total items failed	3

MOT #16 2024-01-02 12:34**MOT test number** 133563933622**Result** ✓ Passed**Next expiry date** 2025-01-02**Advice** Manufactures engine and body covers fitted restricting inspection of components**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #15** 2024-01-02 12:34**MOT test number** 197601010328**Result** ✗ Failed**Pass with rectification** Headlamp aim too low both (4.1.2 (a))**Advice** Central Exhaust mounting defective (6.1.2 (a))**Advice** Manufactures engine and body covers fitted restricting inspection of components**Pass with rectification** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2023-01-03 16:52**MOT test number** 267857771866**Result** ✓ Passed**Advice** Nearside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2022-09-22 08:10**MOT test number** 174578017259**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #12** 2021-10-11 08:22**MOT test number** 112855080705**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Deterioration to front lower arm bushes.**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front tyres devoid of tread on edges.**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-09-23 13:51**MOT test number** 258815443451**Result** ✓ Passed**MOT #10** 2019-10-10 09:46**MOT test number** 470769324149**Result** ✓ Passed

**MOT #9** 2018-10-09 10:10**MOT test number** 500379453925**Result** ✓ Passed**MOT #8** 2017-10-10 10:03**MOT test number** 918349894544**Result** ✓ Passed**MOT #7** 2016-10-06 09:18**MOT test number** 324779873237**Result** ✓ Passed**MOT #6** 2015-10-05 13:10**MOT test number** 912612041109**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear tyre worn badly inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front tyre worn badly inner edge**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-10-15 10:18**MOT test number** 937858484211**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #4** 2013-10-09 15:17**MOT test number** 477232883224**Result** ✓ Passed**MOT #3** 2012-10-09 12:56**MOT test number** 695133082261**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-10-09 12:56**MOT test number** 467343382200**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-10-10 09:55**MOT test number** 467883881285**Result** ✓ Passed**Notice** Front tyres wearing on inner edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 January 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-17
Last registration	2024-01-02
Complete history	See info



Registration #1	2008-10-17	23 mi
Registration #2	2011-10-10	32.959 mi
Registration #3	2012-10-09	40.793 mi
Registration #4	2013-10-09	50.161 mi
Registration #5	2014-10-15	60.232 mi
Registration #6	2015-10-05	69.701 mi
Registration #7	2016-10-06	75.977 mi
Registration #8	2017-10-10	81.636 mi
Registration #9	2018-10-09	86.975 mi
Registration #10	2019-10-09	92.314 mi
Registration #11	2020-10-09	97.653 mi
Registration #12	2021-10-09	102.992 mi
Registration #13	2022-10-09	108.331 mi
Registration #14	2023-10-09	113.670 mi
Registration #15	2024-01-02	119.009 mi
Registration #16		
Registration #17		

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1728 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

456032