





report date: 2024-03-29

General information

Make	BMW
Model	440 440I M SPORT GRAN COUPE
Colour	Blue
Year of manufacture	2018
Top speed	155 mph
0 - 60 mph	5.1 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	322 BHP
Max. torque	450 Nm at 1.380 rpm
Engine capacity	2.998 cc
Cylinders	6
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	171 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 4

Date	2023-06-05
Pictures	0
Listing price	<u>View report</u>

source: carcraft.co.uk

Entry 3

Date	2023-04-29
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 2

Date	2023-04-26	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

Entry 1

Date	2021-10-20	
Pictures	10	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-02-16
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	6
Total items failed	8

MOT #4	2024-02-17 10:57
MOT test number	621671606416
Result	✓ Passed
Next expiry date	2025-02-16
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))	

MOT #3	2022-11-22 11:42
MOT test number	173431445464
Result	✓ Passed

		V 1 0.000 0.
MOT #2		2021-09-20 15:05
MOT test num	ber	100244459537
Result		✓ Passed
Advice Re	ar Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/11



Advice

Fail

PK68BHD

report date: 2024-03-29

MOT #1 2021-09-06 12:01 904014937913 **MOT** test number Result × Failed Fail Offside Front Road wheel has a welding defect (5.2.2 (a)) **Advice** Offside Rear Nail in tyre Fail Nearside Rear Road wheel fractured (5.2.2 (a)) Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i)) Fail Nearside Rear Road wheel fractured (5.2.2 (a)) Fail Nearside Front Road wheel has a welding defect (5.2.2 (a)) Nearside Front Outer Tyre has ply or cords damaged (5.2.3 (d) (ii)) Fail Fail Nearside Rear Inner Road wheel has a welding defect (5.2.2 (a)) **Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i)) Offside Rear Road wheel fractured (5.2.2 (a)) Fail

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Nearside Rear Road wheel fractured (5.2.2 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	16 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
First licence fee (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

α	vner	hi	ctc	1
\cup	viiei	ш	SIL	ע ונ

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report $\underline{\mathbf{k}}$		ve?
manage of the same		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-09-28
Last registration	2024-02-17
Complete history	See info



Registration #1	2018-09-28	20 mi
Registration #2	2021-09-06	36.011 mi
Registration #3	2021-09-20	37.115 mi
Registration #4		11.777 es
Registration #5	2022-11-22	42.646 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
S0569	

Dimensions & weight

Width	1825 mm
Height	1397 mm
Length	4640 mm
Wheel base	2810 mm
Kerb weight	1615 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	18105513

CarCheck.co.uk page 11/11