



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Blue
Year of manufacture	2006
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-19
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	63
Total items failed	17

MOT #21	2023-06-30 10:33
MOT test number	898200525458
Result	✓ Passed
Next expiry date	2024-06-29

MOT #20	2022-06-20 10:44
MOT test number	727042057277
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-06-08 11:32

**MOT test number**

790534496009

**Result****✗ Failed****Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Exhaust has a minor leak of exhaust gases front flexi and rear silencer. (6.1.2 (a))

**DANGEROUS**

Offside Rear Anti-roll bar linkage missing (5.3.3 (a) (ii))

**MAJOR**

Nearside Front Headlamp insecure (4.1.1 (c))

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Front exhaust bracket loose but not dangerous. (flexi)

**MOT #18**

2021-09-11 09:14

**MOT test number**

712890359462

**Result****✓ Passed**

**MOT #17**

2021-09-07 13:56

**MOT test number**

316564077834

**Result****✗ Failed**

- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- DANGEROUS** Offside Rear Brake valve leaking such that brake functionality is affected caliper (1.1.7 (d) (ii))
- MAJOR** Offside Headlamp light intensity severely reduced (4.1.4 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- DANGEROUS** Nearside Rear Anti-roll bar linkage pin or bush likely to become detached (5.3.4 (a) (ii))
- MAJOR** Offside Oil leaking excessively from engine (8.4.1 (a) (i))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))

**MOT #16**

2020-09-21 16:00

**MOT test number**

639025339978

**Result****✓ Passed**

- Advice** Fluid leak, but not excessive Power Steering (8.4.1 (a) (i))
- Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #15**

2019-04-25 16:19

**MOT test number**

246694619825

**Result**

✓ Passed

**Advice**

Rear Exhaust mounting defective (6.1.2 (a))

**Minor**

Front Windscreen wiper blade defective (3.4 (b) (i))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice**

Nearside Rear Nail in tyre

**Advice**

Front Exhaust mounting defective (6.1.2 (a))

**Advice**

Power steering component has slight seepage from a component rack (2.1.5 (a))

**MOT #14**

2019-04-25 12:49

**MOT test number**

509349517652

**Result**

✗ Failed

**MAJOR**

Oil leaking excessively from engine (8.4.1 (a) (i))

**Minor**

Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice**

Nearside Rear Nail in tyre

**Advice**

Power steering component has slight seepage from a component rack (2.1.5 (a))

**Advice**

Rear Exhaust mounting defective (6.1.2 (a))

**Minor**

Front Windscreen wiper blade defective (3.4 (b) (i))

**MAJOR**

Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Advice**

Front Exhaust mounting defective (6.1.2 (a))

**Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #13**

2018-05-02 12:31

**MOT test number**

781275794846

**Result**

✓ Passed

- Advice** Clutch pedal rubber missing
- Advice** Front Exhaust hanger broken
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Cambelt due??

**MOT #12**

2018-04-23 11:02

**MOT test number**

462476003482

**Result**

✗ Failed

- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Engine oil topped up 1 ltr
- Advice** Oil leak
- Fail** Nearside Rear Mechanical brake component has restricted free movement binding (3.5.1k)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Advice** Cambelt due??
- Advice** Power steering fluid level low, but not below minimum (2.3.1)
- Advice** Front Exhaust hanger broken
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both corroded (3.5.1i)
- Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Advice** Clutch pedal rubber missing
- Fail** Power steering component(s) leaking steering rack (2.3.3b)

**MOT #11**

2017-04-19 13:35

**MOT test number**

246563610997

**Result**

✓ Passed

- Advice** Oil leak
- Advice** Headlamp deteriorated but light output not reduced both (1.7.5a)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Bonnet retaining device slightly deteriorated (8.4.2)
- Advice** Power steering component(s) has slight seepage from a component rack (2.3.3b)

**MOT #10**

2017-04-13 12:36

**MOT test number**

298899608830

**Result**

✗ Failed

- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Rear reflector missing (1.5.1a)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Bonnet retaining device slightly deteriorated (8.4.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front brake application uneven (3.7.B.2)
- Advice** Headlamp deteriorated but light output not reduced both (1.7.5a)
- Advice** Power steering component(s) has slight seepage from a component rack (2.3.3b)
- Advice** Oil leak
- Advice** Front Brake pad(s) wearing thin (3.5.1g)





<b>MOT #9</b>	2016-04-12 08:40
<b>MOT test number</b>	574135568763
<b>Result</b>	✓ Passed
<b>Advice</b>	Child seats fitted

<b>MOT #8</b>	2016-04-11 13:15
<b>MOT test number</b>	958713239544
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Registration plate lamp not working (1.1.C.1d)
<b>Fail</b>	Offside Front Suspension arm has excessive play in a pin/bush aft bush (2.4.G.2)
<b>Pass with rectification</b>	Offside Front position lamp(s) not working (1.1.A.3b)
<b>Fail</b>	Nearside Front Suspension arm has excessive play in a pin/bush aft bush (2.4.G.2)
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (8.2.3)
<b>Advice</b>	Child seats fitted

<b>MOT #7</b>	2015-04-07 14:42
<b>MOT test number</b>	225667295053
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #6</b>	2014-03-27 11:59
<b>MOT test number</b>	517986584085
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2013-03-06 16:24
<b>MOT test number</b>	198395663011
<b>Result</b>	✓ Passed



MOT #4	2013-03-05 15:16
MOT test number	449494063067
Result	✗ Failed
Fail	Offside Front Brake hose excessively damaged (3.6.B.4d)
MOT #3	2011-09-22 13:17
MOT test number	387945361280
Result	✓ Passed
MOT #2	2010-09-13 13:45
MOT test number	574986350287
Result	✓ Passed
MOT #1	2009-09-04 08:58
MOT test number	321967049214
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 May 2025

✓  
**MOT**  
  
Expires:  
29 June 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	29 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-14
Last registration	2023-06-30
Complete history	<a href="#">See info</a>



Registration #1	2006-09-14	9 mi
Registration #2	2009-09-04	18.473 mi
Registration #3	2010-09-13	22.190 mi
Registration #4	2011-09-22	26.828 mi
Registration #5	2013-03-05	34.261 mi
Registration #6	2013-03-06	34.261 mi
Registration #7	2014-03-27	38.918 mi
Registration #8	2015-04-07	42.354 mi
Registration #9	2016-04-11	58.556 mi
Registration #10	2016-04-12	58.556 mi
Registration #11	2017-04-13	67.318 mi
Registration #12	2017-04-19	67.318 mi
Registration #13	2018-04-20	76.080 mi
Registration #14	2019-04-21	84.842 mi
Registration #15	2020-04-22	93.604 mi
Registration #16	2021-04-23	102.366 mi
Registration #17	2022-04-24	111.128 mi
Registration #18	2023-04-25	119.890 mi
Registration #19	2023-06-30	128.652 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	6M21092