



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	White
Year of manufacture	2013
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 4


Date	2022-01-19
Pictures	22
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 3

Date	2022-01-17
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date	2021-10-21
Pictures	1
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-10-19
Pictures	1

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #11	2023-12-14 11:39
MOT test number	350920412329
Result	✓ Passed
Next expiry date	2024-12-19
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT #10	2022-12-20 11:12
MOT test number	252702039868
Result	✓ Passed
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #9	2022-01-21 16:34
MOT test number	939452843506
Result	✓ Passed
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #8** 2020-09-30 13:05**MOT test number** 690906324197**Result** ✓ Passed**MOT #7** 2020-09-29 14:42**MOT test number** 500445642505**Result** ✗ Failed**MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-10-16 09:17**MOT test number** 779389452057**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #5** 2019-10-16 09:17**MOT test number** 830105544206**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #4	2018-10-10 09:33
MOT test number	944946783152
Result	✓ Passed
MOT #3	2017-10-11 09:55
MOT test number	432481424237
Result	✓ Passed
MOT #2	2017-10-11 09:55
MOT test number	431070818505
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)
MOT #1	2016-10-17 14:32
MOT test number	116260100999
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2024

✓

MOT

Expires:
19 December 2024

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-10-25
Last registration	2023-12-14
Complete history	See info



Registration #1	2013-10-25	8 mi
Registration #2	2016-10-17	44.295 mi
Registration #3	2017-10-11	51.269 mi
Registration #4	2017-10-11	51.269 mi
Registration #5	2018-10-10	59.681 mi
Registration #6	2019-10-16	69.007 mi
Registration #7	2019-10-16	69.007 mi
Registration #8	2020-09-29	76.651 mi
Registration #9	2020-09-29	76.651 mi
Registration #10	2020-09-29	76.651 mi
Registration #11	2020-09-29	76.651 mi
Registration #12	2020-09-29	76.651 mi
Registration #13	2020-09-29	76.651 mi
Registration #14	2020-09-29	76.651 mi
Registration #15	2020-09-29	76.651 mi
Registration #16	2020-09-29	76.651 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDDU319599