



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 THP DSPORT PLUS
Colour	Black
Year of manufacture	2014
Top speed	133 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	240 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.2 mpg
CO2 emission	135 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-22
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-04
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	35
Total items failed	0

MOT #14	2023-12-05 14:45
MOT test number	808201663831
Result	✓ Passed
Next expiry date	2024-12-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-12-01 16:04
MOT test number	848494426960
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2022-12-05 14:44
MOT test number	956667884368
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))

**MOT #11** 2022-12-05 13:11**MOT test number** 776788901490**Result** ✗ Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Clip snapped (6.1.7 (g) (ii))

Advice Exhaust has a minor leak of exhaust gases Flexi pipe (6.1.2 (a))

MAJOR Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #10 2021-11-29 16:20**MOT test number** 894231887138**Result** ✓ Passed**MOT #9** 2021-07-26 12:04**MOT test number** 928519854867**Result** ✓ Passed**MOT #8** 2021-06-11 15:05**MOT test number** 987602367448**Result** ✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear exhaust mount broken

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Exhaust emits smoke/steam on acceleration but not excessive

MOT #7 2020-07-31 11:36**MOT test number** 131925686845**Result** ✓ Passed

Advice Rear exhaust bracket broken, but exhaust is secure

**MOT #6** 2020-07-30 08:35**MOT test number** 548150334542**Result** ✗ Failed**MAJOR** Offside Front Coil spring with an unsafe modification catching on body (5.3.1 (d) (i))**Advice** Rear exhaust bracket broken, but exhaust is secure**MOT #5** 2019-11-19 10:19**MOT test number** 274283419347**Result** ✓ Passed**Advice** Rear discs surface corroded**Advice** Both rear tyres low**Advice** O/s/f tyre just legal**MOT #4** 2019-11-18 15:57**MOT test number** 926417933604**Result** ✗ Failed**Advice** O/s/f tyre just legal**Advice** Rear discs surface corroded**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Both rear tyres low

**MOT #3**

2019-06-13 09:24

MOT test number

737918629534

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3 (d) (ii))
- Advice** Rear exhaust mounting broken but still adequately supported
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

MOT #2

2018-06-15 11:31

MOT test number

931615563854

Result

✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing BOTH perished (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and tyre valve perished (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

2017-06-14 07:42

MOT test number

670088852316

Result

✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
4 December 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-09-11
Last registration	2023-12-05
Complete history	See info



Registration #1	2014-09-11	8 mi
Registration #2	2017-06-14	14.497 mi
Registration #3	2018-06-15	21.748 mi
Registration #4	2019-06-13	30.601 mi
Registration #5	2019-11-18	33.716 mi
Registration #6	2019-11-19	33.716 mi
Registration #7	2020-07-30	41.141 mi
Registration #8	2020-07-31	41.141 mi
Registration #9	2020-07-31	41.141 mi
Registration #10	2020-07-31	41.141 mi
Registration #11	2020-07-31	41.141 mi
Registration #12	2020-07-31	41.141 mi
Registration #13	2020-07-31	41.141 mi
Registration #14	2020-07-31	41.141 mi
Registration #15	2020-07-31	41.141 mi
Registration #16	2020-07-31	41.141 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1165 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FJBS2096569