



E0I7BLK

report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | NISSAN |
| Model | LEAF ACENTA |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 87 mph |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| | |
|-------------|----------------------|
| Power | 107 BHP |
| Max. torque | 254 Nm at 10.500 rpm |
| Fuel type | Electricity |



LABEL UNKNOWN



Internet history

Entry 1

Date 2021-08-14

Pictures 11

Listing price [View report](#)



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-13 |
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #10 | 2023-09-12 16:08 |
| MOT test number | 230758356195 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-13 |

| | |
|-----------------|--|
| MOT #9 | 2022-09-01 07:47 |
| MOT test number | 351557634906 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge tread worn uneven and tread low on outer edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #8 | 2021-09-14 14:29 |
| MOT test number | 732869993770 |
| Result | ✓ Passed |
| Advice | Offside Rear Outer Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #7 | 2021-09-13 14:40 |
| MOT test number | 914096754843 |
| Result | ✗ Failed |
| Fail | Nearside Front Outer Tyre has a tear, caused by separation or partial failure of its structure Side wall (5.2.3 (d) (ii)) |
| Advice | Offside Rear Outer Tyre worn close to legal limit/worn on edge Edge (5.2.3 (e)) |

**MOT #6** 2020-06-23 14:25**MOT test number** 799202622636**Result** ✓ Passed**MOT #5** 2020-06-23 10:22**MOT test number** 600044450869**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Offside Rear Nail in tyre**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2019-11-15 18:17**MOT test number** 611040209869**Result** ✓ Passed**MOT #3** 2019-05-10 13:02**MOT test number** 850224504642**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2018-11-14 12:15**MOT test number** 272798163537**Result** ✓ Passed**MOT #1** 2018-05-17 12:02**MOT test number** 128049754431**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 September 2024

✓
MOT

Expires:
13 September 2024

Tax status

Valid until 1 September

Days left

125

MOT expiry date

13 September 2024

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this NISSAN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 12 |
| First mileage registration | 2017-03-31 |
| Last registration | 2023-09-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2017-03-31 | 11 mi |
| Registration #2 | 2018-05-17 | 13.868 mi |
| Registration #3 | 2018-11-14 | 27.503 mi |
| Registration #4 | 2019-05-10 | 47.183 mi |
| Registration #5 | 2019-11-15 | 59.665 mi |
| Registration #6 | 2020-06-23 | 68.438 mi |
| Registration #7 | 2020-06-23 | 68.438 mi |
| Registration #8 | 2020-06-23 | 68.438 mi |
| Registration #9 | 2020-06-23 | 68.438 mi |
| Registration #10 | 2020-06-23 | 68.438 mi |
| Registration #11 | 2020-06-23 | 68.438 mi |
| Registration #12 | 2020-06-23 | 68.438 mi |

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 83% |
| Pedestrian | 65% |
| Safety systems | 84% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1550 mm |
| Length | 4445 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1538 kg |
| Max. allowed weight | 1945 kg |

Additional information

| | |
|-----------------|----------------|
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |

| | |
|---------------|---------|
| Engine number | 082481Z |
|---------------|---------|