





report date: 2024-03-28

# General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2013
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/12



# Internet history

## Entry 3

Date 2021-12-08

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date 2021-09-15

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 1

Date 2021-09-08

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-28
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #11	2023-12-06 10:46
MOT test number	986890013679
Result	<b>✓</b> Passed
Next expiry date	2024-12-28

MOT #10	2022-12-29 15:56	
MOT test number	703488479651	
Result	<b>✓</b> Passed	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #9	2021-09-02 14:16
MOT test number	238091505825
Result	✓ Passed
Minor Windscreen wiper blade defective (3.4 (b) (i))	
Advice Front and side undertrays fitted	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



Result

VK13YHJ report date: 2024-03-28

× Failed

MOT #8 2021-09-01 17:45

**MOT test number** 256151981767

**Advice** Front and side undertrays fitted

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Windscreen wiper blade defective (3.4 (b) (i))

**DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #7 2020-09-24 10:31

**MOT test number** 984798034293

Result \square Passed

**MOT #6** 2019-05-01 10:29

**MOT test number** 381938510671

Advice Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #5** 2018-05-01 13:06

**MOT test number** 918359713943

Result \( \sqrt{Passed} \)

**Advice** Offside Front Inner Road wheel with a slightly distorted bead rim rim (4.2.A.1a)

**Advice** Offside registration lamp barely efficient

CarCheck.co.uk page 4/12



✓ Passed

MOT #4 2018-05-01 09:18
MOT test number 269601992437

Result × Failed

Advice Offside registration lamp barely efficient

Advice Offside Front Inner Road wheel with a slightly distorted bead rim rim (4.2.A.1a)

**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 235/35zr19 91y xl (4.1.D.1a)

MOT #3 2017-05-10 12:46

**MOT test number** 603665977623

**Result** ✓ Passed

MOT #2 2017-05-10 08:41

**MOT test number** 749871104401

Result X Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)

**MOT #1** 2016-05-06 09:34

**MOT test number** 114025445525

**Advice** Nearside Front nail in tyre

Result

CarCheck.co.uk page 5/12



## Tax & MOT check



Expires: 28 December 2024

мот

Tax status Expired at 1 February 2024

Days left 89 days too late

MOT expiry date 28 December 2024

Full MOT history See MOT history

## Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



# Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1


Date
Category
Type

Damage 2

Date

**Category** 

**Type** 



#### Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

# Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
***************************************	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



## Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-05-07
Last registration	2023-12-06
Complete history	See info



Registration #1	2013-05-07	18 mi
Registration #2	2016-05-06	32.088 mi
Registration #3	2017-05-10	33.265 mi
Registration #4	2017-05-10	33.265 mi
Registration #5	2018-05-01	38.996 mi
Registration #6	2018-05-01	38.997 mi
Registration #7	2019-05-01	40.364 mi
Registration #8	2020-09-24	48.684 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		

More info >

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



# Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	2
CarChaeleeaule	no and 10/11

CarCheck.co.uk page 12/12

Number of seats	4
Number of axles	2
Engine number	CFHC520511