




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI CDTI 150
Colour	Black
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	315 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	48.7 mpg
CO2 emission	157 g/km
CO2 label	G





## Internet history

### Entry 1

Date	2021-07-31
Pictures	7
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2021-10-28
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	6
Total items failed	13

MOT #13	2020-10-29 18:21
MOT test number	978874872103
Result	✓ Passed
Next expiry date	2021-10-28

MOT #12	2019-06-05 13:09
MOT test number	891319116036
Result	✓ Passed

MOT #11	2018-05-19 08:32
MOT test number	331293924921
Result	✓ Passed

MOT #10	2018-05-18 14:34
MOT test number	716286266295
Result	✗ Failed
<b>Fail</b>	Offside Rear coil spring broken (2.4.C.1a)
<b>Fail</b>	Offside Front coil spring broken (2.4.C.1a)
<b>Fail</b>	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



MOT #9 2017-05-26 15:25

MOT test number 728028718399

Result ✔ Passed

MOT #8 2016-04-08 17:12

MOT test number 388757387356

Result ✔ Passed

MOT #7 2016-04-08 10:07

MOT test number 609991212416

Result ✘ Failed

- Fail Nearside Front Brake pad(s) has restricted free movement heavy corrosion on inner brake disc (3.5.1k)
- Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail Front Windscreen wiper does not clear the windscreen effectively both sides (8.2.2)
- Fail Offside Front Brake pad(s) has restricted free movement heavy corrosion on inner brake disc (3.5.1k)
- Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #6 2015-04-23 09:17

MOT test number 865813915170

Result ✔ Passed

- Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #5 2014-04-22 10:02

MOT test number 395972214149

Result ✓ Passed

MOT #4 2013-04-11 13:25

MOT test number 169211303187

Result ✓ Passed

MOT #3 2013-04-09 10:16

MOT test number 346069893028

Result ✗ Failed

- Fail** Offside Rear position lamp(s) incorrect colour (1.1.A.3e)
- Fail** Offside Rear fog lamp emits a light other than red (1.3.2e)
- Fail** Offside Stop lamp emits other than a steady red light (1.2.1e)
- Fail** Direction indicator incorrect colour (1.4.A.2f)

MOT #2 2012-04-14 13:07

MOT test number 728135502166

Result ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Wipers smearing

MOT #1 2011-04-20 15:21

MOT test number 465010011121

Result ✓ Passed



Tax & MOT check

**×**  
**Untaxed**

**Tax expired:**  
20 October 2021

**×**  
**MOT**

**Expired:**  
28 October 2021

<b>Tax status</b>	Expired at 20 October 2021
<b>Days left</b>	923 days too late
<b>MOT expiry date</b>	28 October 2021
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



**Finance check**

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


<b>Finance company</b>	XXXXXXXX XX
<b>Date of agreement</b>	XXXXXXXX XX
<b>Agreement type</b>	XXXXXXXX XX
<b>Agreement term</b>	XXXXXXXX XX
<b>Agreement number</b>	XXXXXXXX XX
<b>Contact info</b>	XXXXXXXX XX

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	15
<b>First mileage registration</b>	2008-03-18
<b>Last registration</b>	2020-10-29
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2008-03-18	19 mi
<b>Registration #2</b>	2011-04-20	77.167 mi
<b>Registration #3</b>	2012-04-14	90.646 mi
<b>Registration #4</b>	2013-04-09	98.208 mi
<b>Registration #5</b>	2013-04-11	98.288 mi
<b>Registration #6</b>	2014-04-22	103.900 mi
<b>Registration #7</b>	2015-04-23	108.861 mi
<b>Registration #8</b>	2016-04-08	112.321 mi
<b>Registration #9</b>	2017-04-08	112.321 mi
<b>Registration #10</b>	2017-04-08	112.321 mi
<b>Registration #11</b>	2017-04-08	112.321 mi
<b>Registration #12</b>	2017-04-08	112.321 mi
<b>Registration #13</b>	2017-04-08	112.321 mi
<b>Registration #14</b>	2017-04-08	112.321 mi
<b>Registration #15</b>	2017-04-08	112.321 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2033 mm
Height	1467 mm
Length	4249 mm
Wheel base	2614 mm
Kerb weight	1346 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17287056