



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF S
Colour	Blue
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	144 g/km
CO2 label	F





MOT history

MOT expiry date	2021-02-10
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	20
Total items failed	2

MOT #9	2020-02-11 13:00
MOT test number	178844444077
Result	✓ Passed
Next expiry date	2021-02-10
Advice	Wheel bearing has slight play Near side front (5.1.3 (a) (i))
Advice	Coil spring corroded Both rear coils (5.3.1 (b) (i))

MOT #8	2020-02-10 14:27
MOT test number	991803699691
Result	✗ Failed
Fail	Brake fluid contaminated (1.8 (a))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Wheel bearing has slight play Near side front (5.1.3 (a) (i))
Advice	Coil spring corroded Both rear coils (5.3.1 (b) (i))

**MOT #7** 2018-09-12 15:18**MOT test number** 157400851951**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-09-06 15:52**MOT test number** 539629168764**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2016-09-17 09:03**MOT test number** 516946099649**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #4** 2015-09-21 11:05**MOT test number** 863951659624**Result** ✓ Passed**Advice** Both front tyres worn on inner edges



MOT #3	2014-09-12 14:25
MOT test number	769765854294
Result	✓ Passed

MOT #2	2013-09-24 12:59
MOT test number	336467363292
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Notice	Under-trays fitted obscuring some underside components

MOT #1	2012-09-11 10:03
MOT test number	707405752209
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
3 February 2021

X

MOT

Expired:
10 February 2021

Tax status	Expired at 3 February 2021
Days left	1181 days too late
MOT expiry date	10 February 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PE59ESN
Plate since	2024-03-29
Current registration	 PE59ESN
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2009-09-25
Last registration	2020-02-11
Complete history	See info



Registration #1	2009-09-25	16 mi
Registration #2	2012-09-11	30.637 mi
Registration #3	2013-09-24	41.102 mi
Registration #4	2014-09-12	57.115 mi
Registration #5	2015-09-21	75.186 mi
Registration #6	2016-09-20	95.277 mi
Registration #7	2017-09-20	115.377 mi
Registration #8	2018-09-20	135.477 mi
Registration #9	2019-09-20	155.577 mi
Registration #10	2020-02-11	175.677 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1142 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAX 206347