



Mercedes-Benz




report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | MERCEDES |
| Model | CLK CLK220 CDI SPORT |
| Colour | Black |
| Year of manufacture | 2009 |
| Top speed | 137 mph |
| 0 - 60 mph | 10.4 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 2.148 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.1 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 43.5 mpg |
| CO2 emission | 183 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-01-14 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-01-26 |
| MOT pass rate | 65 % |
| MOT passed | 13 |
| Failed MOT tests | 7 |
| Total advice items | 17 |
| Total items failed | 26 |

| | |
|------------------|------------------|
| MOT #20 | 2024-01-11 14:16 |
| MOT test number | 639061954953 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-26 |

| | |
|-----------------|------------------|
| MOT #19 | 2023-01-05 11:11 |
| MOT test number | 337835760626 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #18 | 2022-01-27 15:42 |
| MOT test number | 334522537581 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #17 | 2021-07-22 07:57 |
| MOT test number | 801032248378 |
| Result | ✓ Passed |
| Advice | Engine oil leak further investigation required |

**MOT #16**

2021-07-20 11:29

MOT test number

452779813301

Result

✗ Failed

Fail Nearside Front Lower Suspension arm pin or bush excessively worn steel arm (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Engine oil leak further investigation required**Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn steel arm (5.3.4 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**MOT #15**

2020-11-03 10:05

MOT test number

509718300779

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2020-11-02 09:00

MOT test number

433363204004

Result

✗ Failed

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13**

2019-11-01 10:07

MOT test number

257716081252

Result

✓ Passed

**MOT #12** 2019-10-29 16:55**MOT test number** 468041931923**Result** ✗ Failed**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Power steering malfunctioning (2.1.5 (a))**Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))**MOT #11** 2018-10-30 13:52**MOT test number** 948443250096**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-10-29 11:04**MOT test number** 890792421712**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Power steering inoperative and steering adversely affected (2.1.5 (c) (ii))

**MOT #9** 2017-11-06 16:06**MOT test number** 954123186261**Result** Passed**MOT #8** 2017-10-31 09:07**MOT test number** 974598282808**Result** Failed

- Fail** Rear brake binding park brake (3.7.B.1)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Brake warning light on
- Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)

MOT #7 2016-11-03 17:45**MOT test number** 867326959319**Result** Passed**MOT #6** 2016-11-03 09:40**MOT test number** 376341307583**Result** Failed

- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Rear Brakes imbalanced across an axle brake binding (3.7.B.5b)

MOT #5 2015-10-09 07:46**MOT test number** 744487516523**Result** Passed

**MOT #4**

2015-10-02 07:55

MOT test number

492737679503

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Under body trays fitted
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Tyre has ply or cords exposed both rear (4.1.D.1b)
- Fail** Brake pad(s) less than 1.5 mm thick rear and pad light on (3.5.1g)

MOT #3

2014-10-03 12:39

MOT test number

808576874214

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Rear tyres cracking at shoulder but no cords exposed

MOT #2

2013-06-17 12:50

MOT test number

809508763192

Result

✓ Passed

MOT #1

2012-07-07 10:12

MOT test number

505509682196

Result

✓ Passed

- Advice** Front brake juddering slightly (3.7.A.2b)
- Advice** Outer Rear Lower Suspension arm has slight play in a pin/bearing (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)



Tax & MOT check

X

Untaxed

Tax expired:
27 April 2024

✓

MOT

Expires:
26 January 2025

| | |
|------------------|---------------------------------|
| Tax status | Expired at 27 April 2024 |
| Days left | 2 days too late |
| MOT expiry date | 26 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XX11XX |
| Plate since | 2024-03-28 |
| Current registration |  XX11XX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 22 |
| First mileage registration | 2009-06-05 |
| Last registration | 2024-01-11 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-06-05 | 6 mi |
| Registration #2 | 2012-07-07 | 39.707 mi |
| Registration #3 | 2013-06-17 | 50.094 mi |
| Registration #4 | 2014-10-03 | 59.215 mi |
| Registration #5 | 2015-10-02 | 65.624 mi |
| Registration #6 | 2015-10-09 | 65.669 mi |
| Registration #7 | 2016-11-03 | 69.720 mi |
| Registration #8 | 2016-11-03 | 69.721 mi |
| Registration #9 | 2017-10-31 | 74.664 mi |
| Registration #10 | 2017-11-06 | 74.961 mi |
| Registration #11 | 2018-10-29 | 86.523 mi |
| Registration #12 | 2019-05-20 | 95.377 mi |
| Registration #13 | 2019-05-20 | 95.377 mi |
| Registration #14 | 2019-05-20 | 95.377 mi |
| Registration #15 | 2019-05-20 | 95.377 mi |
| Registration #16 | 2019-05-20 | 95.377 mi |
| Registration #17 | 2019-05-20 | 95.377 mi |
| Registration #18 | 2019-05-20 | 95.377 mi |
| Registration #19 | 2019-05-20 | 95.377 mi |
| Registration #20 | 2019-05-20 | 95.377 mi |
| Registration #21 | 2019-05-20 | 95.377 mi |
| Registration #22 | 2019-05-20 | 95.377 mi |

More info >



Dimensions & weight

| | |
|-------------|---------|
| Width | 1991 mm |
| Height | 1415 mm |
| Length | 4652 mm |
| Wheel base | 2715 mm |
| Kerb weight | 1595 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | 64696630637445 |