



report date: 2024-03-28

General information

Make	CITROEN
Model	DS4 E-HDI AIRDREAM DSTYLE
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-11-21
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-21
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #12	2023-11-23 15:01
MOT test number	506064167999
Result	✓ Passed
Next expiry date	2024-12-21
Advice	Front brake pads 75% worn

MOT #11	2023-11-23 10:06
MOT test number	730941876056
Result	✗ Failed
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Front brake pads 75% worn
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10	2022-12-20 14:32
MOT test number	373568725990
Result	✓ Passed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Slightly insecure (6.1.7 (g) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.45mm (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.26mm (5.2.3 (e))

**MOT #9** 2022-12-19 16:16**MOT test number** 786272116488**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2.45mm (5.2.3 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Slightly insecure (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/18 2.26mm (5.2.3 (e))**MOT #8** 2021-12-18 11:27**MOT test number** 507269973457**Result** ✓ Passed**Advice** Bay covers fitted**MOT #7** 2020-12-14 15:55**MOT test number** 955816744269**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #6** 2020-12-14 15:55**MOT test number** 958237625032**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



**MOT #5** 2019-12-19 13:01**MOT test number** 415272029675**Result** ✓ Passed**MOT #4** 2018-12-19 11:43**MOT test number** 120083403348**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-12-21 14:13**MOT test number** 567281406997**Result** ✓ Passed**MOT #2** 2017-12-21 12:49**MOT test number** 269513964315**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2016-12-22 11:40**MOT test number** 227696570426**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
21 December 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	21 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-12-17
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2013-12-17	8 mi
Registration #2	2016-12-22	42.272 mi
Registration #3	2017-12-21	57.783 mi
Registration #4	2017-12-21	57.783 mi
Registration #5	2018-12-19	71.243 mi
Registration #6	2019-12-19	79.640 mi
Registration #7	2020-12-14	83.361 mi
Registration #8	2021-12-14	83.361 mi
Registration #9	2021-12-14	83.361 mi
Registration #10	2021-12-14	83.361 mi
Registration #11	2021-12-14	83.361 mi
Registration #12	2021-12-14	83.361 mi
Registration #13	2021-12-14	83.361 mi
Registration #14	2023-11-23	83.361 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	80%
Pedestrian	43%
Safety systems	97%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	JBFV0026377