





report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D4 SE NAV
Colour	Red
Year of manufacture	2014
Top speed	137 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 2

Date 2021-02-04

Pictures 29

Listing price <u>View report</u>










source: yesauto.com

Entry 1


Date	2021-01-29
Pictures	29

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



BG14VCW report date: 2024-03-28

MOT history

MOT expiry date	2024-07-27
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #8	2023-07-12 08:27
MOT test number	976027797495
Result	✓ Passed
Next expiry date	2024-07-27
Advice Rear heat shield cover loose	

MOT #7		2022-07-28 13:38
MOT test	number	397530644166
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #6	2022-01-17 11:29
MOT test number	845019675748
Result	✓ Passed
MOT #5	2021-01-30 07:32
MOT test number	819771591909
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2020-07-21 14:06

MOT test number 116615636311

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2019-05-01 11:31

MOT test number 201416282284

MOT #2 2018-02-16 16:36

MOT test number 129912645456

Result ✓ Passed

MOT #1 2017-04-19 10:04

MOT test number 171663497600

Result
✓ Passed

Advice Central Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
---------------	--

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	UK SIE
Plate since	
Current registration	NIA.
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-05-09
Last registration	2023-07-12
Complete history	See info



Registration #1	2014-05-09	29 mi
Registration #2	2017-04-19	72.286 mi
Registration #3	2018-02-16	80.104 mi
Registration #4	2019-05-01	80.279 mi
Registration #5	2020-07-21	102.265 mi
Registration #6		11.777 es
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		19.397 mg

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1722 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number1046726