





report date: 2024-03-28

General information

Make	BMW
Model	X4 XDRIVE20D M SPORT
Colour	Grey
Year of manufacture	2015
Top speed	132 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2021-10-10

Pictures 14

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date	2021-10-06
Pictures	6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



OO65AKB report date: 2024-03-28

MOT history

MOT expiry date	2025-02-19
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #10		2024-02-20 10:40
MOT test	number	616004434783
Result		✓ Passed
Next expi	ry date	2025-02-19
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2023-01-13 10:01
MOT test number	372933343083
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))	

MOT #8	2022-01-20 12:00
MOT test number	931522574246
Result	✓ Passed

MOT #7	2022-01-19 14:33
MOT test number	414335729493
Result	× Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6

MOT test number

620908548749

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2020-12-10 09:15 **MOT** test number 484011351027 Result **X** Failed Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 245/45/19 (5.2.3 (d) (i)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

806175290893

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Tyre worn close to legal limit/worn on edge 245/45/19 (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3 2019-11-18 15:11
MOT test number 411742886814

Result × Failed

Advice Rear brake pads very low

Advice Leak on both rear diff seals

Fail Nearside Front Headlamp aim too low and too far to the left. (4.1.2 (a))

Advice Punture in nearside front tyre

Advice Slight movement in offside front rack

MOT #2 2018-10-29 16:36

MOT test number 368170673856

Result ✓ Passed

MOT #1 2018-10-25 14:39

MOT test number 550383949954

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords large chunk cut on inner sidewall (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



OO65AKB report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	19 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-11-28
Last registration	2024-02-20
Complete history	See info



Registration #1	2015-11-28	21 mi
Registration #2	2018-10-25	30.829 mi
Registration #3	2018-10-29	30.831 mi
Registration #4	2019-11-18	41.208 mi
Registration #5	2019-12-03	41.392 mi
Registration #6	2020-12-10	48.834 mi
Registration #7	2020-12-10	48.834 mi
Registration #8		11.177 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		11.177 es
Registration #12		0.00 44
Registration #13		70.777 esc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	53%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1881 mm
Height	1624 mm
Length	4671 mm
Wheel base	2810 mm
Kerb weight	1745 kg
Max. allowed weight	2335 kg

Additional information

Fuel tank capacity	67 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles2Engine number51579342