





## General information

Make	MAZDA
Model	2 SE-L NAV PLUS
Colour	Blue
Year of manufacture	2018
Top speed	117 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	89 BHP
Max. torque	148 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption combined	49.6 mpg
CO2 emission	111 g/km
CO2 label	С





### Internet history


Entry 3	
Date	2021-12-17
Pictures	4
Listing price	View report



source: autoonline.co.uk

Entry 2	
Date	2021-12-11
Pictures	0
Listing price	View report
source: heycar.co.uk	
Entry 1	
Date	2021-12-10
Pictures	4

Listing price





source: cargurus.co.uk







## MOT history

MOT expiry date	2024-09-07
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #4	2023-09-05 13:52
MOT test number	906356216723
Result	✓ Passed
Next expiry date	2024-09-07

MOT #3	2022-09-02 07:48
MOT test number	535041314305
Result	Passed
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply of (i))	r cords Multiple cuts (5.2.3 (d)

MOT #2	2022-09-01 14:	14	
MOT test nu	imber 1897589094	)6	
Result	× Faile	ed	
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))			
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))			
<b>Advice</b> 0	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
<b>Advice</b> 0	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice N(i))	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Multiple cuts (5.2.3 (	3)	
Advice N	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
<b>Advice</b> N	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		





MOT #1	2021	09-08 12:40
MOT test I	number 39	0361704238
Result		✓ Passed
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d)	(i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords $(5.2.3 (d)$	(i))



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 July 2024	<b>Expires:</b> 7 September 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
	4	
Date		1.E
Category		amt
Туре		

#### Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





## Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-08
Last registration	2023-09-05
Complete history	See info



Registration #1	2018-09-08	12 mi
Registration #2	2021-09-08	17.031 mi
Registration #3		11.777 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		10.300 est





# Safety ratings

NCAP rating	****
Adult	86%
Children	78%
Pedestrian	84%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1695 mm
Height	1495 mm
Length	4060 mm
Max. allowed weight	1510 kg
Additional information	
Number of seats	5
Number of axles	2
Engine number	P5 20511582