



report date: 2024-03-28

General information

Make	MAZDA
Model	CX-5 D SE-L NAV
Colour	Blue
Year of manufacture	2012
Top speed	126 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 1.800 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-05-24
Pictures	6
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	25
Total items failed	6

MOT #13	2024-02-23 09:44
MOT test number	352191241279
Result	✓ Passed
Next expiry date	2025-02-22

MOT #12	2023-01-26 08:31
MOT test number	110686809483
Result	✓ Passed
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11**

2022-02-14 16:09

**MOT test number**

103239780889

**Result**

✓ Passed

- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear suspension arms corroded
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2022-02-14 10:46

**MOT test number**

231919746725

**Result**

✗ Failed

- Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Nail in tyre
- Advice** Rear suspension arms corroded
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9** 2021-02-19 09:08**MOT test number** 196182371262**Result** ✓ Passed**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement n/s & o/s (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened n/s & o/s (1.1.14 (a) (ii))**MOT #8** 2020-01-03 17:16**MOT test number** 462769427740**Result** ✓ Passed**MOT #7** 2019-01-04 09:41**MOT test number** 539994892417**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))**MOT #6** 2018-01-08 16:03**MOT test number** 612934642605**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2018-01-08 16:03**MOT test number** 252379231958**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

**MOT #4** 2016-10-31 08:43**MOT test number** 844602184021**Result** ✓ Passed**Advice** Engine and under covers fitted, partial examination only**MOT #3** 2016-10-31 08:34**MOT test number** 872254861386**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Engine and under covers fitted, partial examination only**MOT #2** 2015-09-16 09:40**MOT test number** 367942328044**Result** ✓ Passed**MOT #1** 2015-09-16 09:40**MOT test number** 405109484999**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
22 February 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	22 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-10-01
Last registration	2024-02-23
Complete history	<a href="#">See info</a>



Registration #1	2012-10-01	14 mi
Registration #2	2015-09-16	70.351 mi
Registration #3	2015-09-16	70.351 mi
Registration #4	2016-10-31	86.065 mi
Registration #5	2016-10-31	86.065 mi
Registration #6	2018-01-08	98.081 mi
Registration #7	2018-01-08	98.081 mi
Registration #8	2019-01-04	109.948 mi
Registration #9	2019-01-04	109.948 mi
Registration #10	2019-01-04	109.948 mi
Registration #11	2019-01-04	109.948 mi
Registration #12	2019-01-04	109.948 mi
Registration #13	2019-01-04	109.948 mi
Registration #14	2019-01-04	109.948 mi
Registration #15	2019-01-04	109.948 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30240566