



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 260 LR P/V
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-05-09
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	39
Total items failed	16

MOT #17	2023-05-10 10:48
MOT test number	244741787514
Result	✓ Passed
Next expiry date	2024-05-09

MOT #16	2022-03-21 16:35
MOT test number	912931333202
Result	✓ Passed
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Slight corrosion on sills and inner sills n/s and o/s not holed at time of test

MOT #15	2021-02-26 13:44
MOT test number	134774184391
Result	✓ Passed
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #14	2020-02-04 12:04
MOT test number	742480106594
Result	✓ Passed

**MOT #13**

2020-02-03 12:29

MOT test number

569376325378

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- DANGEROUS** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #12

2019-02-27 10:53

MOT test number

750461042452

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner facing (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner facing (1.1.14 (a) (ii))

**MOT #11** 2019-02-27 10:53**MOT test number** 835730380515**Result** ✗ Failed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner facing (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Inner facing (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

MOT #10 2018-02-22 10:48**MOT test number** 857311021114**Result** ✓ Passed

- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner facing (3.5.1i)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

MOT #9 2018-02-22 10:48**MOT test number** 768440030341**Result** ✗ Failed

- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner facing (3.5.1i)
- Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Pass with rectification** Central Stop lamp not working (1.2.1b)

**MOT #8**

2017-01-20 17:45

MOT test number

858398347889

Result

✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner facing scored (3.5.1i)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner rear bush (2.4.G.2)

MOT #7

2017-01-19 17:49

MOT test number

566420805370

Result

✗ Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Rear Body has a sharp edge caused by damage lamp lens (6.1.C.1)

Fail Nearside Body has a sharp edge caused by damage door mirror backing (6.1.C.1)

Fail Offside Rear brake disc in such a condition that it is seriously weakened inner facing (3.5.1i)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Offside Obligatory mirror missing (8.1.1)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement inner rear bush (2.4.G.2)

Fail Offside Body has a sharp edge caused by damage door mirror backing (6.1.C.1)

Fail Front brake disc modified and seriously weakened worn to excess (3.5.1n)

MOT #6

2016-01-28 14:30

MOT test number

895915076796

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2014-11-12 15:31**MOT test number** 556616414361**Result** ✓ Passed**MOT #4** 2014-11-11 12:44**MOT test number** 309595414374**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Both front lower arm rear bushes poor condition**Fail** Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Offside rear tyre leaking**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**MOT #3** 2014-02-06 15:06**MOT test number** 138527934066**Result** ✓ Passed**MOT #2** 2013-06-24 15:27**MOT test number** 595165073137**Result** ✓ Passed**MOT #1** 2012-06-18 10:03**MOT test number** 408910972134**Result** ✓ Passed**Advice** Direction indicator slightly discoloured (1.4.A.2f)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
9 May 2024

Tax status		Valid until 1 December
Days left		217
MOT expiry date		9 May 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-26
Last registration	2023-05-10
Complete history	See info



Registration #1	2009-06-26	21 mi
Registration #2	2012-06-18	27.761 mi
Registration #3	2013-06-24	38.391 mi
Registration #4	2014-02-06	44.463 mi
Registration #5	2014-11-11	51.498 mi
Registration #6	2014-11-12	51.500 mi
Registration #7	2016-01-28	70.367 mi
Registration #8	2017-01-19	82.592 mi
Registration #9	2017-01-20	82.602 mi
Registration #10	2019-05-20	95.377 mi
Registration #11	2019-05-20	95.377 mi
Registration #12	2019-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2360 mm
Height	1989 mm
Length	4863 mm
Kerb weight	1699 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	9R16420